



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 3154J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REAR O/S & N/S TAIL LAMP	NOT NECESSARY	800.00	-
2	REAR O/S & N/S TAIL LAMP BRACKET	NOT NECESSARY	430.20	-
1	REAR TAIL GATE (CHENGAL)	NOT NECESSARY	3,000.00	-
4	REAR TAIL GATE HINGES	NOT NECESSARY	320.00	-
2	REAR TAIL GATE O/S & N/S LOCK	NOT NECESSARY	410.00	-
2	REAR TAIL GATE O/S & N/S LOCK LEVER HANDLE	NOT NECESSARY	210.00	-
1	REAR REG NUMBER PLATE LAMP	NOT NECESSARY	210.40	-
	LESS 10% DISCOUNT		-538.06	-
			4,842.54	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAIL GATE '60 KMPH' EMBLEM (SN)	NOT NECESSARY	15.00	-
1	REAR TAIL GATE '24 PAX' EMBLEM (SN)	NOT NECESSARY	15.00	-
1	REAR REVERSE CAMERA (SN)	DAMAGED	800.00	350.00
2	REAR O/S & N/S WOODEN MEMBER (CHENGAL) (SN)	NOT NECESSARY	1,600.00	-
1	REAR STEP (WOODEN)(SN)	CRACKED	200.00	200.00
1	REAR LTA GUARD (SN)	NOT NECESSARY	1,600.00	-
1	REAR REG NUMBER PLATE (SN)	DENTED	35.00	35.00
			4,265.00	585.00
	<u>LABOUR</u>			
	TO DISMANTLE,STRAIGHTEN AND WELDING .		1,400.00	200.00
	TO SPRAY PAINTING.		500.00	200.00
	TO CHECK WIRING .		80.00	30.00
			1,980.00	430.00
	GRAND TOTAL		11,087.54	1,015.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00

Report Ref No. CS/AGI22010808/Awy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.