

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | |
|---|---|--|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Ref: | CS/AGI22010808/Awy3q2 | |
| | | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | Date: | 13/02/2023 | |
| | | | Code: | AGI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SLC 2477L | Veh. Inspected | YQ 3154J | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | C10018327/CD | Excess (\$) | 0.00 | |
| | Assign From | MAYBIE CHUA | Assign Date | 31/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HINO XZU710R | c.c | 4009 | |
| | Engine No. | HIDDEN | Year of Reg. | 2021 | |
| | Chassis No. | JHHUCV3F10K036481 | Colour | WHITE | |
| | Odometer | 93601 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | NIL | |
| | General | GOOD | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195/85 R16 | BRIDGESTONE | 6 mm | |
| | L/H Front Tyre | 195/85 R16 | BRIDGESTONE | 6 mm | |
| | R/H Rear Tyre | 195/85 R16 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 195/85 R16 | BRIDGESTONE | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 28/10/2022 | Inspection Date | 08/11/2022 | |
| | Survey held at | RYDER AUTO PTE LTD | | | |
| | | 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921 | | | |
| 5a. | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: