

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/GRB22010810/SVY3E2**Date:** 07/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : GBE4050D **Insured Vehicle No :** SLS5273D
 Date of Loss: 26/10/2022 Nature of Claim: TP Claim No: MFL2022D0006564

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE4050D**
 Make & Model: TOYOTA DYNA, 3.0 D (M) Engine No: 1KD2553622
 Reg. Date: 25/11/2015 (Man. Year: 2015) Chassis No: KDY2318021471
 Colour: White Odometer: 278153 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R13
 Front Left Side: Energy Van 5 mm Rear Left Side: Energy Van 6 mm
 Front Right Side: Energy Van 5 mm Rear Right Side: Energy Van 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/10/2022
 Date Inspected: 31/10/2022 Inspected At: EVOLUTION96 AUTO PTE LTD (HQ)
 3020A UBI ROAD 1, #01-33
 Singapore 408714
 Estimated Period of Repair: 0.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Nov 2022)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE4050D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >