



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 5658E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR METAL BUMPER	BENT	680.00	680.00
2	SET BRACKET FOR METAL BUMPER @\$255.00	BENT	510.00	510.00
2	REAR RUBBER STOPPER (BUMPER) @\$195.00	CRACKED	390.00	390.00
2	NO CHASSIS RUNNER @\$380.00	O/S BENT	760.00	380.00
4	NO ALUMINIUM CAPPING @\$480.00	NECESSARY	1,920.00	1,920.00
4	NO PVC CORNER CAPPING @\$180.00	NECESSARY	720.00	720.00
1	NO UV TREATED GRP BOARD FOR THE EXTERIOR OF THE REAR BOX	CRACKED	1,000.00	1,000.00
15	NO SEALANT TUBE @\$25.00	NECESSARY	375.00	375.00
			6,355.00	5,975.00
	<u>LABOUR</u>			
	LOGO WRITING ON REAR REF BOX (EXACTLY SAME AS OLD BOX).		800.00	600.00
	TO SUPPLY LABOUR TO INSTALL AND FIBER GLASS REPAIR FOR ALUMINIUM CAPPING ,CORNER CAPPING AND GPR BOARD.		300.00	180.00
	TO SUPPLY LABOUR AND MATERIAL TO PAINT BLACK THE REAR METAL BUMPER,BRACKET AND CHASSIS BRACKET.		750.00	400.00
	TO ADJUST AND LEVELLING REFRIGERATED BOX.		800.00	500.00
	TO SUPPLY LABOUR AND MATERIAL TO INSTALL AND TIG WELDING REAR METAL BUMPER WITH BRACKET AND CHASSIS BRACKET .		1,500.00	800.00
			4,150.00	2,480.00
	GRAND TOTAL		10,505.00	8,455.00
	RECOMMENDED COST OF REPAIR SUM			8,000.00

Report Ref No. CS/SMO22010811/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.