



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010811/Kvy3q2	
			Date: 06/12/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 3748B	Veh. Inspected	GBC 5658E
	Policy No.	D22MTPCVE002416	Coverage (\$)	0.00
	Claim No.	CMTD2203885/MYE	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	31/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	JTFAT35Y00K202165	Colour	SILVER
	Odometer	285335 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/75 R15	YOKOHAMA	8 mm
	L/H Front Tyre	195/75 R15	YOKOHAMA	8 mm
	R/H Rear Tyre	155 R12X8 (D)	LANVIGATOR	8/8 mm
	L/H Rear Tyre	155 R12X8 (D)	LANVIGATOR	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/10/2022	Inspection Date	03/11/2022
	Survey held at	SYSTEMATIC AIRCONDITIONING PTE LTD 29 SENOKO WAY SINGAPORE 758059		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	