

ASS. R. = UBI Taujin

REF: CS/SPF 22010813/Twy 3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP/WS / TP RES / OD RES / EVA / INV / MV
 To Insp. Ext Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

Veh No: FBS3363J Yr Regn: 2021, March
 Type: M. Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha Xmax C.C. 250
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MH35G3910 LR 034231
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: NIL / S/Rim / STD A/Rim or _____
 Tyre Size: F: 120/70 R14
 R: 140/70 R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIRI / SUMI /
 TOYO / YOKO or _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$16K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS W/-
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 2/11/22
 Survey held at Eurat Lee Motor
 Des. of Damages Ft / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>lifum workshop repair limit \$7000.</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B.R. (\$) _____

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date:

2-Nov-22

Estimate no.

1177

Plate No. FBS3363J

Model. XMAX300

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 900.00	bt - 600	
2	FORK T-UNDER BRACKET	\$ 450.00	bt - 200	
3	STEERING CONE	\$ 280.00	ne - 150	
4	FRONT SPORT RIM	\$ 650.00	mis - 400	
5	FRONT TYRES	\$ 220.00	mis - 180	
6	FRONT TYRES SHAFT	\$ 180.00	mis - 100	
7	FRONT BEARINGS X2	\$ 80.00	mis -	
8	FRONT CALIPER	\$ 250.00	dis - 200	
9	FRONT SPEEDO ABS CABLE	\$ 120.00	dis -	
10	FRONT BRAKE HOSE	\$ 180.00	dis -	
11	WIRE HARNESS SET	\$ 850.00	X } un	
12	BATTERY BOX	\$ 250.00	X } un	
13	BATTERY	\$ 150.00	X } un	
14	HEAD LIGHT	\$ 1,200.00	mis - 600	
15	HEAD LAMP STAY	\$ 500.00	bt - 200	
16	METER	\$ 950.00	X un	
17	WINDSHIELD	\$ 280.00	mis - 180.	
18	WINDSHIELD COVER X2	\$ 150.00	ent - 100	
19	WINDSHIELD BRACKET X2	\$ 180.00	bt - 120	
20	ABS PUMP	\$ 1,500.00	X un	
21	HANDLE BAR	\$ 200.00	bt - 150	
22	MIRROR SET	\$ 250.00	ent - 120	
23	BRAKE LEVEL RIGHT	\$ 100.00	ent - 60	
24	HANDLE COVER 1	\$ 180.00	de - 100	
25	HANDLE COVER 2	\$ 150.00	de - 100	
26	HANDLE BAR END	\$ 120.00	ent - 60	
27	FRONT FAIRING COVER RIGHT	\$ 280.00	dis - 180	
28	FRONT FAIRING COVER LEFT	\$ 280.00	mis - 180	
29	FRONT FAIRING PANEL COVER RIGHT	\$ 200.00	de - 100	
30	FRONT FAIRING PANEL COVER LEFT	\$ 200.00	de - 100	

4560

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 2-Nov-22

Estimate no.

1177

Plate No. FBS3363J

Model. XMAX300

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
31	PANEL COVER 1	\$ 150.00	de ✓	
32	PANEL COVER 2	\$ 120.00	de ✓	
33	INNER PANEL	\$ 280.00	7m ✓ 180	
34	METER PANEL COVER	\$ 200.00	? and ✓ 140	
35	HORN SWITCH	\$ 250.00	7m ✓	
36	BODY UNDER COVER	\$ 320.00	dis ✓ 250	
37	RIADIRATOR	\$ 500.00	bt ✓ 400	
38	FOOTREST BOARD COVER LEFT	\$ 220.00	dis ✓ 180	
39	FOOTREST BOARD UNDER COVER LEFT	\$ 180.00	dis ✓ 120	
40	FOOTREST RUBBER LEFT	\$ 80.00	mis ✓	
41	REAR FOOTREST LEFT	\$ 120.00	bro ✓	
42	RIADIRATOR FAN	\$ 180.00	7m ✓	
43	ALARM SWITCH SENSOR	\$ 180.00	7m ✓	
44	FRONT FENDER	\$ 150.00	mis ✓	
45	FRONT FENDER SIDE COVER X2	\$ 120.00	dis ✓	
46	FRONT FOOTREST BOARD COVER RIGHT	\$ 220.00	dis ✓ 120	
47	FRONT FOOTREST BOARD UNDER COVER	\$ 180.00	dis ✓	
48	FRONT COMPARTMENT BOX RIGHT	\$ 150.00	bro ✓	
49	HANDLE BRACKET	\$ 300.00	bt ✓ 150	
50	IGNITION KEY	\$ 400.00	7m ✓ 200	
51	FRONT NUMBER PLATE	\$ 30.00	mis ✓	
52	EXHAUST PIPE	\$ 950.00	xm ✓	
53	EXHAUST COVER 1	\$ 100.00	cut ✓	
54	EXHAUST COVER 2	\$ 80.00	cut ✓	
55	REAR FOOTREST RIGHT	\$ 120.00	cut ✓ 60	
56	REAR FOOTREST BRACKET RIGHT	\$ 100.00	7m ✓	
57	REAR NUMBER PLATE	\$ 30.00	bt ✓	
58	MAINSTAND	\$ 350.00	bt ✓ 150	
59	REAR FOOTREST BRACKET LEFT	\$ 100.00	bro ✓ 50	

3490

Less 10% \$ 1,744.00

\$ 17,440.00

Sub Total : \$ 15,696.00

GST 7% \$ 1,098.72

Total: \$ 16,794.72

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Estimate no.

1177

Date: 2-Nov-22

Plate No. FBS3363J

Model. XMAX300

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
60	REAR FAIRING COVER RIGHT	\$ 280.00	ant-180	
61	REAR FAIRING COVER LEFT	\$ 280.00	ant-180	
62	RACK	\$ 300.00	bro-150	
63	BOX	\$ 550.00	bro-300	
64	REAR FAIRING CENTER COVER	\$ 150.00	x nn	
65	CVT COVER	\$ 180.00	ant-120	
66	AIR BOX COVER	\$ 150.00	ant-100	
67	BODY ALIGNMENT - labour	\$ 500.00	200/3 pinto.	
68	REAR MADGUARD	\$ 200.00	x nn	
69	REAR SUSPENSION	\$ 800.00	x nn	2180
70	ENGINE MOUNTING	\$ 500.00	7bt-250	
71	SPRAY COVERSET - labour	\$ 700.00	500	
72	ENGINE CRANKCASE SET	\$ 1,800.00	crank to check price 900	
73	LABOUR	\$ 1,000.00	600	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL:

\$16 794.72 + \$7116.57 = \$23 911.29

Tanjong 97495749/62563561
WP' 2/11/22 @ 3pm
L/S Resurvey after repair
* To check repair limit
- To check consistency of accident
- To check part prices

8-10 days
Repair limit \$7000

Parts 4560
3490
2180

Less 10% \$ 739.00
\$ 7,390.00
Sub Total : \$ 6,651.00
GST 7% \$ 465.57
Total: \$ 7,116.57

10230
10% - 9207
labour 200
500
600
1300
9207
1300
10507
L/S \$8400

1300 Repair limit \$7000

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

L/S \$7000
10 days