



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22010813/Twy3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	30/03/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 315P	Veh. Inspected	FBS 3363J
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/062	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	31/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA XMAX	c.c	250
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MH3SG3910LK034231	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	120/70 R14	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R14	MICHELIN	5 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	03/06/2022	Inspection Date	02/11/2022
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	