



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7652Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	439.04	-
1	FRONT DOOR RH	BENT	1,160.10	1,160.10
1	FRONT DOOR RH INNER TRIM BOARD	NOT NECESSARY	672.60	-
	LESS 30% DISCOUNT		-	-348.03
			2,271.74	812.07
<u>NETT ITEMS</u>				
1	FRONT RH FENDER SIGNAL LAMP (N)	NOT NECESSARY	36.70	-
1	FRONT RH DOOR WINGMIRROR (N)	GRAZED	343.00	343.00
1	FRONT RH DOOR OUTER HANDLE (N)	GRAZED	95.00	95.00
1	FRONT RH DOOR OUTER HANDLE KEY LOCK (N)	NOT NECESSARY	85.00	-
1	FRONT RH DOOR LOCK (N)	NOT NECESSARY	138.70	-
1	FRONT RH DOOR WEATHERSTRIP (N)	NECESSARY	57.00	57.00
1	FRONT RH DOOR FRAME BLACK STICKER (N)	NECESSARY	21.00	21.00
1	FRONT RH DOOR CHECKER (N)	NOT NECESSARY	34.60	-
2	FRONT RH DOOR HINGE @\$46.70 (N)	NOT NECESSARY	93.40	-
	LESS 10% DISCOUNT		-	-51.60
			904.40	464.40
<u>SPECIAL NETT ITEMS</u>				
1	FRONT SPORT RIM RH (SN)	BENT	450.00	300.00
			450.00	300.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE-REFIT, CUT-WELD, PANEL BEAT,STRAIGHTEN ,RE-ALIGN AND REPAIR OF FRONT RH FENDER, FRONT RH DOOR, AND ALL RELEVANT ACCIDENT DAMAGES. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		1,200.00	400.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	TO TRANSFER RH DOORS FITTINGS AND ATTACHMENTS.		80.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENT TO AFFECTED PANELS.		150.00	60.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		1,000.00	500.00
			2,560.00	1,090.00
GRAND TOTAL			6,186.14	2,666.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS1/SPF22010814/Rny3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,100-\$2,300

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.