

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22010815/TVY3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SLL1620Z**Insured Vehicle No :** SLL787H

Date of Loss: 27/10/2022

Nature of Claim:

TP

Claim No: DMPC2200519H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLL1620Z**

Make & Model: ADIVA AD1 200, 190cc 3W

Engine No: 27191031343665

Reg. Date: 21/02/2011 (Man. Year: 2010)

Chassis No: WDD2040452A496059

Colour: Blue

Odometer: 150510 km

Engine Capacity: 1597 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,733.30	3,789.70	1,943.60	33.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,250.00	830.00	39.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,813.30	5,039.70	2,773.60	35.50
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	7,813.30	4,050.00	3,763.30	48.17
+ GST 8.00/8.00% (S\$)	625.06	324.00	301.06	48.16
Nett Amount (S\$)	8,438.36	4,374.00	4,064.36	48.17

INSPECTION

Date of Assignment: 31/10/2022

Date Inspected: 01/11/2022 Inspected At:

Em-1 Auto Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate Sector C, #01-68
Singapore 575643

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Feb 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL1620Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID BADGE	Necessary	62.00 FL	*62.00 FL
2	1		*BOOT LID EMBLEM C180	Necessary	85.00 FL	*85.00 FL
3	1		*BOOT LID EMBLEM KOMPRESSOR	Necessary	108.00 FL	*108.00 FL
4	1		*REAR BUMPER	Deformed	1,472.00 FL	*1,472.00 FL
5	1		*REAR BUMPER SIDE RETAINERS	O/S Cracked	132.00 FL	*66.00 FL
6	1		*REAR BUMPER ATTACHMENT RETAINERS	O/S Distorted	150.00 FL	*75.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
8	1		*REAR BUMPER CENTER RETAINERS	Cracked	196.00 FL	*196.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	705.00 FL	*599.00 FL
10	1		*REAR BUMPER CENTER CHROME MOULDING	Cut	197.00 FL	*197.00 FL
11	2		*REAR BUMPER SIDE CHROME MOULDING	Necessary	324.00 FL	*324.00 FL
12	1		*TAILLAMP	Cracked	759.00 FL	*699.00 FL
13	1		*SET TAILLAMPS CLIPS	Not Necessary	25.00 FL	*- FL
14	1		*END PANEL	Repair	1,297.00 FL	*- FL
15	1		*END PANEL TOP TRIM	Not Necessary	145.00 FL	*- FL
16	1		*SET END PANEL TOP TRIM CLIPS	Not Necessary	30.00 FL	*- FL
17	4		*REVERSE SENSOR	Not Working	450.00 FS	*250.00 FS
18	1		*SET BODY PANEL JOINT SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,307.00	4,183.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	573.70	393.30
Total Parts (\$\$)	5,733.30	3,789.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	500.00
2	SPRAY PAINTING	New	900.00	600.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	60.00	30.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	90.00	60.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
Gross Labour Cost (S\$)			2,080.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >