



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9516H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	BROKEN	170.00	170.00
1	FRONT BUMPER O/S RETAINER (WCP)	BROKEN	10.00	10.00
1	FRONT BUMPER LOWER LID (WCP)	CUT	120.00	120.00
1	FRONT O/S HEADLAMP (WCP)	BROKEN	910.00	910.00
1	FRONT O/S FOG LAMP (WCP)	NOT NECESSARY	115.00	-
1	FRONT O/S FOG LAMP GRILLE (WCP)	CUT	15.00	15.00
1	FRONT O/S FENDER (WCP)	DENTED	180.00	180.00
1	FRONT O/S FENDER INNER SHIELD (WCP)	NOT NECESSARY	75.00	-
10	FRONT O/S FENDER INNER SHIELD CLIPS @\$3.00 (WCP)	NOT NECESSARY	30.00	-
1	FRONT O/S WHEEL ARCH GARNISH (WCP)	CUT	45.00	45.00
	COST PLUS 10%		167.00	145.00
			1,837.00	1,595.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS ,KNOCK OUT ,CUT WELD BODY PANEL PARTS WHERE NECESSARY ,STRAIGHTEN AND RESHAPE ,REPOSITION AND REALIGN RE-PLACEMENT PARTS TO THE ORIGINAL POSITION.		680.00	500.00
	SPRAY PAINTING OF ACCIDENT SECTIONS.		680.00	600.00
			1,360.00	1,100.00
GRAND TOTAL			3,197.00	2,695.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00
LESS EXCESS			-250.00
NETT LIABILITY			1,900.00

Report Ref No. CS/SMO22010818/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.