

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS22010820/EVY3M4**Date:** 08/03/2023**REFERENCE**

Insured/Claimant:	OW KIM LENG, VINCENT	Policy No:	0
Date of Loss:	17/10/2022	Nature of Claim:	OD Claim No: 202222007511

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMA2598U</b>	Engine No:	8ARZ122484
Make & Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Chassis No:	JTEZB3GH70J002123
Reg. Date:	31/05/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/60 R15	Rear Tyre Size:	225/60 R15
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,694.00	896.50	797.50	47.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	400.00	450.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,544.00</b>	<b>1,296.50</b>	<b>1,247.50</b>	<b>49.04</b>
<b>- Excess (S\$)</b>	0.00	600.00	-600.00	
<b>(S\$)</b>	2,544.00	696.50	1,847.50	72.62
<b>+ GST 7.00/7.00% (S\$)</b>	178.08	48.76	129.32	72.62
<b>Nett Amount (S\$)</b>	<b>2,722.08</b>	<b>745.26</b>	<b>1,976.82</b>	<b>72.62</b>

**INSPECTION**

Date of Assignment:	31/10/2022	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	24/11/2022	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	3.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
<b>Parts:</b> M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA2598U)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Broken	750.00 F	*750.00 F
2	1		*REAR BUMPER LOWER GARNISH (WCP)	Not Necessary	330.00 F	*- F
3	1		*REAR BUMPER SENSOR (WCP)	Not Necessary	220.00 F	*- F
4	1		*REAR BUMPER SIDE BRACKET RH (WCP)	Broken	40.00 F	*40.00 F
5	1		*REAR BUMPER RETAINER RH (WCP)	Not Necessary	65.00 F	*- F
6	10		*REAR BUMPER CLIPS (WCP)	Necessary	25.00 F	*25.00 F
7	1		*REAR BUMPER SIDE SHIELD RH (WCP)	Not Necessary	110.00 F	*- F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>1,540.00</b>	<b>815.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	154.00	81.50
<b>Total Parts (S\$)</b>	<b>1,694.00</b>	<b>896.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>REAR FENDER AIR VENT RH - TO CHECK</b> (NPA) (Not Necessary)	-	0.00
2	1	<b>REAR FENDER RH - TO REPAIR</b> (NPA) (Repair)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	<b>TO REPAIR REAR FENDER RH, REMOVE &amp; REFIX DAMAGED PARTS, STRAIGHTEN &amp; REALIGN AFFECTED AREA</b>	New	350.00	200.00
2	<b>TO SPRAY REAR FENDER RH, REAR BUMPER &amp; AFFECTED AREAS</b>	New	500.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>850.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**