

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010835/PA3Q2
Date: 14/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070008693
Claimant Vehicle No :	SMH4313A	Insured Vehicle No :	SMR5493D
Date of Loss:	01/11/2022	Nature of Claim:	TP
		Claim No:	1875365362SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH4313A	Engine No:	MR20447677C
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0011980
Reg. Date:	23/01/2019 (Man. Year: 2018)	Odometer:	45138 km
Colour:	Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,788.69	10,586.36	5,202.33	32.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,450.00	2,610.00	4,840.00	64.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,238.69	13,196.36	10,042.33	43.21
+ GST 7.00/7.00% (S\$)	1,626.71	923.75	702.96	43.21
Nett Amount (S\$)	24,865.40	14,120.11	10,745.29	43.21
+ Car Rental (7.0 x S\$150.00/day + 7.00% GST) (S\$)		1,123.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,245.61		

INSPECTION

Date of Assignment:	02/11/2022		
Date Inspected:	02/11/2022	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Distorted / Cracked	4,728.00 FN	*4,728.00 FN
2	1		*REAR BOOT COVER EMBLEM X-TRAIL	Necessary	118.70 FN	*118.70 FN
3	1		*REAR BOOT COVER LOGO	Not Necessary	70.00 FN	*- FN
4	1		*REAR BOOT COVER LOCK	Not Necessary	662.10 FN	*- FN
5	2		*REAR BOOT COVER ELECTRICAL DAMPER L&RH	Damaged / Leaking	2,717.20 FN	*2,470.20 FN
6	2		*REAR BOOT COVER HINGE L&RH	Not Necessary	77.60 FN	*- FN
7	1		*REAR BOOT COVER W/STRIP	Twisted	167.20 FN	*167.20 FN
8	1		*REAR BOOT COVER REFLECTOR L&RH	O/S Cracked	825.80 FN	*412.90 FN
9	1		*REAR BOOT COVER WINDSCREEN GLASS	Not Necessary	1,495.20 FN	*- FN
10	1		*REAR BOOT COVER WINDSCREEN MOULDING	Necessary	75.10 FN	*75.10 FN
11	1		*REAR BOOT COVER INNER BOARD WITH CLIPS	Not Necessary	511.90 FN	*- FN
12	1		*REAR BUMPER FASCIA	Distorted	748.60 FN	*748.60 FN
13	1		*REAR BUMPER SIDE RETAINER L&RH	O/S Cracked	84.00 FN	*42.00 FN
14	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FN	*35.00 FN
15	1		*REAR BUMPER REFLECTOR L&RH	O/S Cracked	133.80 FN	*66.90 FN
16	1		*REAR BUMPER REINFORCEMENT BEAM	Distorted	643.30 FN	*643.30 FN
17	1		*REAR BUMPER CHROME	Cracked	185.20 FN	*185.20 FN
18	1		*TAIL LAMP RH	Cracked	825.80 FN	*825.80 FN
19	1		*REAR FENDER RH	Repair	1,247.60 FN	*- FN
20	1		*REAR FENDER WHEEL ARCH GARNISH RH	Not Necessary	175.50 FN	*- FN
21	1		*REAR END PANEL	Badly Dented	483.70 FN	*483.70 FN
22	1		*REAR END PANEL INNER GARNISH	Distorted	85.00 FN	*85.00 FN
23	1		*REAR FENDER QUARTER GLASS RH	Not Necessary	432.00 FS	*- FS
24	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
25	1		*SET REAR BUMPER PARKING SENSOR	Shorted	380.00 FS	*200.00 FS
26	2		*REAR BUMPER BRACKET L&RH	Bent / Dented	422.80 FN	*422.80 FN
27	1		*REAR BUMPER INNER SIDE GARNISH LH	Missing	30.00 FN	*30.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	17,446.10	11,740.40
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,657.41	1,154.04
Total Parts (\$\$)	15,788.69	10,586.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT RENEW KNOCKING ,WELDING ,STRAIGHTEN & REALIGN REAR END PANEL ,REAR BOOT TUB FLOOR PANEL ,REAR LAMP PANEL ,RH REAR FENDER ,RH REAR CHASSIS PILLAR ,ALL AFFECTED PARTS & ETC	New	3,200.00	1,000.00
2	REMOVE & REFIX REAR BOOT MECHANICAL LOCK ASSY ,CENTRAL LOCKING SYSTEM,WIPER MOTOR ASSY ,ELECTRICAL DAMPER	New	180.00	100.00
3	REMOVE & REFIX FUEL TANK ASSY TO FACILITATE REPAIRS	New	250.00	0.00
4	REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
5	REMOVE & REFIX REAR QUARTER GLASS	New	120.00	0.00
6	REMOVE & REFIX INTERIOR UPHOLSTERY ,ROOF LINING ,SEATS ,CARPETS ,FURNISHER ,TRIMMING ,SAFETY BELT ,ALL AFFECTED PARTS & ETC	New	280.00	100.00
7	PLACE VEHICLE ON MEASURING BENCH	New	480.00	0.00
8	SPRAY PAINTING ON DAMAGE PARTS	New	1,900.00	1,100.00
9	TUFF-KOTE ON DAMAGE PARTS	New	180.00	60.00
10	CHECK WATER SEEPING AFTER REPAIRS	New	120.00	0.00
11	REMOVE & REFIX REAR BUMPER SENSOR	New	280.00	50.00
12	CHECK ALL WIRING & LIGHTING AFTER REPAIRS	New	80.00	30.00
13	DIAGNOSIS CHECK & RESET AFTER REPAIRS	New	200.00	50.00
Gross Labour Cost (S\$)			7,450.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >