

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010836/KPA3Q2**Date:** 16/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800020341
Claimant Vehicle No :	SMM7174M	Insured Vehicle No :	SLW7602D
Date of Loss:	29/10/2022	Nature of Claim:	TP
		Claim No:	7030191277SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7174M		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0D80768
Reg. Date:	11/07/2019 (Man. Year: 2019)	Chassis No:	ZWR800391245
Colour:	Metallic Black	Odometer:	252610 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,050.35	7,375.40	1,674.95	18.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	2,190.00	930.00	29.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,170.35	9,565.40	2,604.95	21.40
+ GST 7.00/7.00% (S\$)	851.92	669.58	182.34	21.40
Nett Amount (S\$)	13,022.27	10,234.98	2,787.29	21.40
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,036.98		
Global Sum Settlement (S\$)		11,000.00		

INSPECTION

Date of Assignment:	01/11/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	01/11/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	7.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,460.50 FL	*1,460.50 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	95.10 FL	*95.10 FL
3	1		*REAR TAILGATE OUTER CHROME GARNISH	Mtg Cracked	839.70 FL	*581.00 FL
4	1		*REAR TAILGATE LOGO EMBLEM	Necessary	72.80 FL	*72.80 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.40 FL	*75.40 FL
6	1		*REAR TAILGATE MECHANISM LOCK	Jammed	435.10 FL	*435.10 FL
7	1		*REAR TAILGATE INNER HANDLE COVER	Dented	32.40 FL	*32.40 FL
8	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Cracked	570.80 FL	*495.10 FL
9	1		*REAR TAILGATE WEATHERSTRIP	Distorted / Dented	220.30 FL	*220.30 FL
10	1		*REAR TAILLAMP LH	Mtg Cracked	876.90 FL	*781.55 FL
11	1		*REAR TAILLAMP RH	Mtg Cracked	876.90 FL	*781.55 FL
12	1		*REAR SIDE GARNISH LH	Buckled	196.40 FL	*196.40 FL
13	1		*REAR SIDE GARNISH RH	Mtg Cracked	196.40 FL	*196.40 FL
14	1		*REAR SIDE GARNISH LOWER BRACKET LH	Repair	142.10 FL	*- FL
15	1		*REAR SIDE GARNISH LOWER BRACKET RH	Serviceable	142.10 FL	*- FL
16	1		*REAR BUMPER	Bent	781.60 FL	*781.60 FL
17	1		*REAR BUMPER SIDE RETAINER LH	Distorted	85.30 FL	*85.30 FL
18	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	85.30 FL	*- FL
19	1		*REAR BUMPER REFLECTOR LH	Cracked	76.30 FL	*76.30 FL
20	1		*REAR BUMPER REFLECTOR RH	Serviceable	76.30 FL	*- FL
21	1		*REAR BUMPER TOWING COVER	Dented	31.20 FL	*31.20 FL
22	1		*REAR BUMPER INNER ANTENNA SENSOR	Serviceable	97.50 FL	*- FL
23	1		*REAR END PANEL	Bent	586.70 FL	*586.70 FL
24	1		*REAR END PANEL TOP GARNISH	Dented	207.10 FL	*207.10 FL
25	1		*REAR FLOOR PANEL	Repair	798.80 FL	*- FL
26	1		*REAR FLOOR PANEL TOP CARD BOARD	Dented / Cracked	830.40 FL	*691.00 FL
27	1		*REAR FENDER INNER TRIM BOARD LH	Buckled	582.20 FL	*582.20 FL
28	1		*REAR FENDER INNER TRIM BOARD RH	Cracked	582.20 FL	*582.20 FL
29	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
30	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
32	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
33	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
34	1		*REAR BUMPER REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
35	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*REAR END PANEL JOINT SEALANT		60.00 FS	*30.00 FS
37	1		*REAR FLOOR PANEL INSULATOR MAT		100.00 FS	*100.00 FS
38	1		*REAR FENDER INNER TRIM BOARD CLIPS LH		50.00 FS	*50.00 FS
39	1		*REAR FENDER INNER TRIM BOARD CLIPS RH		50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,813.80	9,637.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,763.45	2,261.80
Total Parts (\$\$)	9,050.35	7,375.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST AT ACCIDENT AREAS	New	1,200.00	900.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	1,200.00	900.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REFIX 3RD ROW SEAT CUSHION & ETC	New	100.00	80.00
6	LABOUR CHARGES TO REMOVE & REFIX REAR EXHAUST SILENCER BOX & ETC	New	100.00	0.00
7	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	50.00
8	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	60.00
9	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (S\$)			3,120.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >