

ASS. REC. BY:

REF:

AIG/ 22010836/kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6-9 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smm 7174m

Yr Regn:

07 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Noah

C.C

1797

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

252610

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZWR80

0391245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F: P1889

195/65R13

R: WST/ALK

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

29/10/22

D.O.I.

1/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Tailgate jammed

16/11 @ 9565.40 Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 01/11/2022

Vehicle No: SMM7174M

Model: TOYOTA NOAH HYBRID 1.8X

Chassis: ZWR800391245 - 2019

Reg.Year: 2019

Third Party Insurer: AIG

Third Party Veh No: SLW7602D

Date of Accident: 29/10/2022

Estimator: KIT

Surveyor:

Not Withheld

89565.40

Recovery After Pair

8 days
7

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1	Per	\$1,460.50
2	REAR TAILGATE WINDSCREEN MOULDING	1	Per	\$95.10
3	REAR TAILGATE OUTER CHROME GARNISH	1	mg cm	\$839.70
4	REAR TAILGATE "LOGO" EMBLEM	1	Per	\$72.80
5	REAR TAILGATE "HYBRID" EMBLEM	1	Per	\$75.40
6	REAR TAILGATE MECHANISM LOCK	1	Per	\$435.10
7	REAR TAILGATE INNER HANDLE COVER	1	Per	\$32.40
8	REAR TAILGATE INNER TRIM BOARD	1	mg cm	\$570.80
9	REAR TAILGATE WEATHERSTRIP	1	DIY	\$220.30
10	REAR TAILLAMP LH	1	mg cm	\$876.90
11	REAR TAILLAMP RH	1	Per	\$876.90
12	REAR SIDE GARNISH LH	1	Per	\$196.40
13	REAR SIDE GARNISH RH	1	mg cm	\$196.40
14	REAR SIDE GARNISH LOWER BRACKET LH	1	R	\$142.10
15	REAR SIDE GARNISH LOWER BRACKET RH	1	Per	\$142.10
16	REAR BUMPER	1	Per	\$781.60
17	REAR BUMPER SIDE RETAINER LH	1	DIY	\$85.30
18	REAR BUMPER SIDE RETAINER RH	1	Per	\$85.30
19	REAR BUMPER REFLECTOR LH	1	cm	\$76.30
20	REAR BUMPER REFLECTOR RH	1	Per	\$76.30
21	REAR BUMPER TOWING COVER	1	Per	\$31.20
22	REAR BUMPER INNER ANTENNA SENSOR	1	Per	\$97.50
23	REAR END PANEL	1	Per	\$586.70
24	REAR END PANEL TOP GARNISH	1	Per	\$207.10
25	REAR FLOOR PANEL	1	R	\$798.80
26	REAR FLOOR PANEL TOP CARD BOARD	1	nd/cm	\$830.40
27	REAR FENDER INNER TRIM BOARD LH	1	Per	\$582.20
28	REAR FENDER INNER TRIM BOARD RH	1	cm	\$582.20
29	REAR FENDER LH	1		REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SUB TOTAL	\$11,053.80
LESS 25%	-\$2,763.45
PARTS TOTAL	\$8,290.35

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Acknowledged by Repairer

Signature: _____
Date: _____

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 01/11/2022
Vehicle No: SMM7174M
Model: TOYOTA NOAH HYBRID 1.8X
Chassis: ZWR800391245 - 2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLW7602D
Date of Accident: 29/10/2022
Estimator: KIT
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		na \$80.00
2	REAR NUMBER PLATE WITH HOLDER	1		na \$50.00
3	REAR TAILGATE INNER TRIM BOARD CLIPS	1		na \$40.00
4	REAR BUMPER CLIPS	1		na \$50.00
5	REAR BUMPER REVERSE SENSOR	1		na \$250.00
6	REAR END PANEL TOP GARNISH CLIPS	1		na \$30.00
7	REAR END PANEL JOINT SEALANT	1		NEC \$60.00
8	REAR FLOOR PANEL INSULATOR MAT	1		NEC \$100.00
9	REAR FENDER INNER TRIM BOARD CLIPS LH	1		NEC \$50.00
10	REAR FENDER INNER TRIM BOARD CLIPS RH	1		NEC \$50.00
S/N TOTAL				\$760.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST AT ACCIDENT AREAS. 900l \$1,200.00

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. 900l \$1,200.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS. \$120.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS. \$120.00

LABOUR CHARGES TO REMOVE & REFIX 3RD ROW SEAT CUSHION & ETC. \$100.00

LABOUR CHARGES TO REMOVE & REFIX REAR EXHAUST SILENCER BOX & ETC. na \$100.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR. \$100.00

TO TUFF KOTE & UNDERSEAL MATERIALS. \$100.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00

LABOUR TOTAL \$3,120.00

KIT TOTAL \$12,170.35

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

