

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22010837/UQY3Q2**Date:** 07/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000659	
Claimant Vehicle No :	SHA2405C	Insured Vehicle No :	SNG2639S	
Date of Loss:	27/10/2022	Nature of Claim:	TP	Claim No: M2206072

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2405C	Engine No:	G4LEKU210484
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU146086
Reg. Date:	14/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,623.20	11,288.40	4,334.80	27.75
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	4,710.00	3,040.00	1,670.00	35.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,344.20	14,339.40	6,004.80	29.52
Approved Total (Overridden) (S\$)		11,400.00		
(S\$)	20,344.20	11,400.00	8,944.20	43.96
+ GST 7.00/7.00% (S\$)	1,424.09	798.00	626.09	43.96
Nett Amount (S\$)	21,768.29	12,198.00	9,570.29	43.96

INSPECTION

Date of Assignment:	31/10/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	01/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2405C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Torn	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER SIDE BRACKET LH	Cracked	55.80 FL	*55.80 FL
4	1		*REAR FENDER LH	Badly Dented	1,768.30 FL	*1,768.30 FL
5	1		*REAR BUMPER AIR DUCT LH	Twisted	87.30 FL	*87.30 FL
6	1		*WHEEL RIM LH	Cracked	1,124.20 FL	*1,124.20 FL
7	1		*WHEEL TYER LH (60%)	Cut	216.00 F	*129.60 F
8	1		*CURTAIN AIRBAG MODULE	Activated	1,344.50 FL	*1,344.50 FL
9	1		*FRT LH SEAT CUSHION }	Buckled	3,151.20 FL	*3,151.20 FL
10	1		*FRT LH SEAT CUSHION AIR BAG }	Activated	1,344.50 FL	*- FL
11	1		*REAR SAFETY BELT ASSY LH	Activated	513.20 FL	*513.20 FL
12	1		*REAR SAFETY BELT ASSY RH	Activated	513.20 FL	*513.20 FL
13	1		*FRT SAFETY BELT ASSY RH	Activated	648.90 FL	*648.90 FL
14	1		*FRT SAFETY BELT ASSY LH	Activated	648.90 FL	*648.90 FL
15	1		*FUEL LIP TANK COVER	Not Necessary	83.30 FL	*- FL
16	1		*REAR WHEEL HUP CAP LH	Repair	346.40 FL	*- FL
17	1		*REAR WHEELBEARING ING \$ HUB	Damaged	544.00 FL	*346.60 FL
18	1		*REAR TRAILING ARM LH	Not Necessary	265.40 FL	*- FL
19	1		*REAR ASSIST ARM LH	Not Necessary	227.90 FL	*- FL
20	1		*REAR S/ABSORBER LH	Bent	230.50 FL	*230.50 FL
21	1		*REAR S/ABSORBER MOUNTING LH	Not Necessary	133.10 FL	*- FL
22	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
23	1		*STABILIZER LINK	Not Necessary	147.30 FL	*- FL
24	1		*REAR UPPER ARM LH	Bent	239.50 FL	*239.50 FL
25	1		*REAR LOWER ARM LH	Not Necessary	393.10 FL	*- FL
26	1		*REAR KNUCKLE ARM LH	Bent	538.10 FL	*538.10 FL
27	1		*UNIT ASSY - SMARTK CRU (RADAR SENSOR)	Not Necessary	1,784.80 FL	*- FL
28	1		*REAR DOOR APPS LOGO	Necessary	80.00 F	*80.00 F
29	1		*REAR FENDER SHIELD LH	Torn	173.60 FL	*173.60 FL
Supplementary #1						
30	1		*ROOF HEADLINING ASSY	Torn	1,983.30 FL	*1,983.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	19,455.00	14,058.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,831.80	2,769.70
Total Parts (\$\$)	15,623.20	11,288.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,800.00	1,050.00
2	SPRAYPAINT	New	1,200.00	1,000.00
3	CHECK WIRING	New	80.00	20.00
4	TUFF KOTE	New	80.00	40.00
5	REMOVE/REFIX REAR UPHOSLTERY	New	200.00	80.00
6	RENEW SAFETY BELT	New	150.00	120.00
7	REMOVE/RENEW FRT SEAT CUSHION LH	New	150.00	50.00
8	REMOVE / REFIX REAR UNDER CARRIGE	New	300.00	180.00
9	DIAGNOSETIC & RESETTING FAULT CODE	New	480.00	280.00
10	TOWING FEE (KING DOOLY)	New	150.00	120.00
11	ADJUST FOUR WHEEL ALIGNMENT	New	120.00	100.00
Gross Labour Cost (\$\$)			4,710.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >