

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22010847/AWY3Q2**Date:** 07/03/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SLP54T**Insured Vehicle No :** PC1044L

Date of Loss: 26/10/2022

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP54T**

Make & Model: TOYOTA HARRIER, 2.0 Elegance (A)

Engine No: 3ZRB674659

Reg. Date: 02/02/2016 (Man. Year: 2015)

Chassis No: ZSU600063403

Colour: White

Odometer: 75680 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size: 235/60 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,671.13	13,634.20	8,036.93	37.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	3,130.00	910.00	22.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,711.13	16,764.20	8,946.93	34.80
Approved Total (Overridden) (S\$)		13,400.00		
(S\$)	25,711.13	13,400.00	12,311.13	47.88
+ GST 8.00/8.00% (S\$)	2,056.89	1,072.00	984.89	47.88
Nett Amount (S\$)	27,768.02	14,472.00	13,296.02	47.88

INSPECTION

Date of Assignment: 31/10/2022

Date Inspected: 01/11/2022 Inspected At:

People's Vehicle Recovery Service (HQ)

Blk 3023A Ubi Rd 1, #01-60

Singapore 408717

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP54T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,819.10 FL	*1,466.00 FL
2	1		*TAILGATE GLASS	Shattered	1,719.20 FL	*1,488.00 FL
3	1		*TAILGATE GLASS MOULDING	Necessary	180.00 FL	*180.00 FL
4	2		*TAILGATE ABSORBER	Not Necessary	385.60 FL	*- FL
5	1		*TAILGATE OUTER HANDLE	Not Necessary	780.10 FL	*- FL
6	1		*TAILGATE OUTER GARNISH	Cracked	1,217.90 FL	*598.00 FL
7	2		*TAILGATE HINGES	Not Necessary	378.40 FL	*- FL
8	1		*TAILGATE LOGO	Necessary	121.30 FL	*121.30 FL
9	1		*TAILGATE HARRIER EMBLEM	Necessary	131.20 FL	*131.20 FL
10	2		*TAILGATE LAMP	Cracked	1,578.60 FL	*900.00 FL
11	1		*TAILGATE INNER LOCK	Jammed	425.30 FL	*425.30 FL
12	1		*TAILGATE INNER BOARD	Deformed	1,018.10 FL	*581.00 FL
13	1		*TAILGATE GLASS INNER SIDE GARNISH	N/S Deformed	570.20 FL	*285.10 FL
14	1		*TAILGATE GLASS INNER TOP GARNISH	Deformed	382.60 FL	*382.60 FL
15	1		*TAILGATE WEATHERSTRIP	Cut	282.00 FL	*282.00 FL
16	1		*WIPER MOTOR REAR	Damaged	978.10 FL	*620.00 FL
17	1		*WIPER ARM REAR	Cut	415.90 FL	*95.00 FL
18	1		*TAIL LAMP	N/S Cracked	1,578.20 FL	*789.10 FL
19	1		*BUMPER REAR	Deformed	1,217.90 FL	*1,217.90 FL
20	2		*BUMPER SIDE RETAINER REAR	Not Necessary	356.20 FL	*- FL
21	1		*BUMPER LOWER GARNISH REAR	Deformed	680.30 FL	*459.00 FL
22	1		*BUMPER REINFORCEMENT REAR	Not Necessary	370.90 FL	*- FL
23	1		*FENDER L/H REAR	Buckled	990.10 FL	*990.10 FL
24	1		*FENDER INNER L/R REAR	Buckled	1,350.00 FL	*867.00 FL
25	1		*TAIL LAMP PANEL L/H	Buckled	650.00 FL	*495.00 FL
26	1		*FENDER INNER GARNISH L/H REAR	Deformed	580.00 FL	*580.00 FL
27	1		*FENDER INNER TOP GARNISH L/H REAR	Not Necessary	285.00 FL	*- FL
28	1		*TOOL BOX GARNISH L/H	Deformed	365.00 FL	*365.00 FL
29	1		*SAFETY BELT REAR	Not Necessary	750.00 FL	*- FL
30	2		*NUMBER PLATE LAMP	Not Necessary	370.00 FL	*- FL
31	1		*END PANEL REAR	Dented	970.10 FL	*786.00 FL
32	1		*END PANEL TOP GARNISH REAR	Deformed	789.10 FL	*361.00 FL
33	1		*TAILGATE SPOILER	Cracked	1,702.58 FS	*1,500.00 FS
34	1		*BUMPER SPONGE REAR	Cracked	220.00 FL	*220.00 FL
35	1		*QUARTER GLASS L/H REAR	Not Necessary	385.00 FL	*- FL
36	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
37	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
38	1		*CAMERA REAR	Missing	650.00 FS	*580.00 FS
39	1		*NUMBER PLATE BASE REAR	Damaged	50.00 FS	*50.00 FS
40	1		*TAILGATE GLASS GUM	Necessary	40.00 FS	*40.00 FS
41	1		*TAILGATE GLASS TINTED	Necessary	280.00 FS	*250.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					27,743.98	17,305.60
- List Item Discount on L Items 25.00/25.00% (\$\$)					6,072.85	3,671.40
Total Parts (\$\$)					21,671.13	13,634.20
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	2,200.00	1,600.00
2	SPRAY PAINTING ACCIDENT AFFECTED PARTS	New	1,200.00	1,100.00
3	REMOVE AND REFIX WINDSCREEN REAR	New	120.00	120.00
4	REMOVE AND REFIT REAR UPHOLSTERY ,CARPET AND ETC	New	180.00	100.00
5	CHECK ALL LIGHTING AFTER REPAIR	New	60.00	30.00
6	COMPUTERIZED WHEEL ALIGNMENT	New	80.00	0.00
7	TOWING CHARGES	New	80.00	80.00
8	UNDERCOAT	New	120.00	100.00
Gross Labour Cost (S\$)			4,040.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >