

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010855/UYA3Q2**Date:** 31/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000047
Claimant Vehicle No :	SLE3348J	Insured Vehicle No :	SLD8212P
Date of Loss:	29/10/2022	Nature of Claim:	TP
		Claim No:	0617297298SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3348J	Engine No:	2ZR1802571
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W60J004655
Reg. Date:	18/07/2016 (Man. Year: 2016)	Odometer:	173427 km
Colour:	Gold		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,514.86	15,998.24	25,516.62	61.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,830.00	4,340.00	7,490.00	63.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,344.86	20,338.24	33,006.62	61.87
Approved Total (Overridden) (S\$)		16,200.00		
Nett Amount (S\$)	53,344.86	16,200.00	37,144.86	69.63
+ Car Rental (17.0 x S\$140.00/day) (S\$)		2,380.00		
Nett Liability (S\$)		18,580.00		

INSPECTION

Date of Assignment:	01/11/2022	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	01/11/2022 Inspected At:	
Estimated Period of Repair:	14.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,589.70 FL	*1,461.10 FL
2	1		*TAILGATE WINDSCREEN	Not Necessary	902.78 FL	*- FL
3	1		*TAILGATE WINDSCREEN MOULDING	Necessary	250.70 FL	*120.00 FL
4	1		*TAILGATE WIPER MOTOR	Not Necessary	485.90 FL	*- FL
5	1		*TAILGATE WIPER ARM	Not Necessary	189.50 FL	*- FL
6	1		*TAILGATE WIPER ARM COVER	Not Necessary	56.30 FL	*- FL
7	1		*TAILGATE GARNISH	Cracked	295.90 FL	*295.90 FL
8	1		*TAILGATE HANDLE SWITCH	Not Necessary	124.06 FL	*- FL
9	1		*TAILGATE LOGO	Necessary	92.80 FL	*78.00 FL
10	1		*TAILGATE VALVE MATIC WORDING	Necessary	55.40 FL	*55.40 FL
11	1		*TAILGATE ELEGANCE WORDING	Necessary	63.90 FL	*63.90 FL
12	1		*TAILGATE NUMBER PLATE LAMP LH	Not Necessary	60.70 FL	*- FL
13	1		*TAILGATE NUMBER PLATE LAMP RH	Not Necessary	60.70 FL	*- FL
14	1		*TAILGATE REFLECTOR LH	Cracked	325.40 FL	*325.40 FL
15	1		*TAILGATE REFLECTOR RH	Cracked	325.40 FL	*325.40 FL
16	1		*TAILGATE HINGE LH	Not Necessary	67.40 FL	*- FL
17	1		*TAILGATE HINGE RH	Not Necessary	67.40 FL	*- FL
18	1		*TAILGATE ABSORBER LH	Not Necessary	269.80 FL	*- FL
19	1		*TAILGATE ABSORBER RH	Not Necessary	269.80 FL	*- FL
20	1		*TAILGATE INNER BOARD	Deformed / Torn	486.10 FL	*486.10 FL
21	1		*TAILGATE LOCK	Dented / Damaged	443.90 FL	*443.90 FL
22	1		*TAILGATE WEATHERSTRIP	Twisted	398.80 FL	*398.80 FL
23	1		*TAILGATE INNER HANDLE	Not Necessary	38.20 FL	*- FL
24	2		*TAILGATE STOPPER	Not Necessary	110.80 FL	*- FL
25	1		*TAIL LAMP LH	Not Necessary	497.70 FL	*- FL
26	1		*TAIL LAMP RH	Not Necessary	497.70 FL	*- FL
27	1		*TAIL LAMP HOLDER LH	Not Necessary	12.50 FL	*- FL
28	1		*TAIL LAMP HOLDER RH	Not Necessary	12.50 FL	*- FL
29	1		*TAIL LAMP PANEL LH	Repair	195.80 FL	*- FL
30	1		*TAIL LAMP PANEL RH	Repair	195.80 FL	*- FL
31	1		*REAR BUMPER	Distorted	595.60 FL	*595.60 FL
32	1		*REAR BUMPER REFLECTOR LH	Cracked	60.40 FL	*60.40 FL
33	1		*REAR BUMPER REFLECTOR RH	Cracked	60.40 FL	*60.40 FL
34	1		*REAR BUMPER RETAINER LONG LH	Bent	95.60 FL	*95.60 FL
35	1		*REAR BUMPER RETAINER LONG RH	Bent	95.60 FL	*95.60 FL
36	1		*REAR BUMPER RETAINER SHORT LH	Not Necessary	69.40 FL	*- FL
37	1		*REAR BUMPER RETAINER SHORT RH	Not Necessary	69.40 FL	*- FL
38	1		*REAR BUMPER IMPACT BRACKET LH	Dented	60.50 FL	*60.50 FL
39	1		*REAR BUMPER IMPACT BRACKET RH	Dented	60.50 FL	*60.50 FL
40	1		*REAR BUMPER SHIELD LH	Not Necessary	85.30 FL	*- FL
41	1		*REAR BUMPER SHIELD RH	Not Necessary	85.30 FL	*- FL
42	1		*REAR END PANEL	Badly Dented	558.74 FL	*558.74 FL
43	1		*REAR END PANEL LOWER	Badly Dented	185.70 FL	*185.70 FL
44	1		*REAR END PANEL TOP GARNISH	Twisted	286.90 FL	*286.90 FL
45	1		*REAR END PANEL SENSOR	Cracked	237.72 FL	*237.72 FL
46	1		*REAR WELL PANEL	Repair	757.10 FL	*- FL
47	1		*REAR WELL PANEL TOP GARNISH	Not Necessary	595.60 FL	*- FL
48	1		*REAR WELL PANEL TOP BOARD	Not Necessary	470.20 FL	*- FL
49	1		*REAR WELL PANEL TOP BOARD LH	Not Necessary	319.20 FL	*- FL
50	1		*REAR WELL PANEL TOP BOARD RH	Not Necessary	319.20 FL	*- FL
51	1		*REAR WELL PANEL SPONGE	Not Necessary	275.60 FL	*- FL
52	1		*REAR CHASSIS FRAME LH	Not Necessary	2,315.60 FL	*- FL
53	1		*REAR CHASSIS FRAME RH	Not Necessary	2,315.60 FL	*- FL
54	1		*REAR FENDER LH	Repair	1,055.80 FL	*- FL
55	1		*REAR FENDER RH	Repair	1,055.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR FENDER GLASS WITH MOULDING LH	Not Necessary	495.70 FL	*- FL
57	1		*REAR FENDER GLASS WITH MOULDING RH	Not Necessary	495.70 FL	*- FL
58	1		*REAR FENDER INNER BOARD LH	Not Necessary	850.50 FL	*- FL
59	1		*REAR FENDER INNER BOARD RH	Not Necessary	850.50 FL	*- FL
60	1		*REAR FENDER AIR VENT LH	Not Necessary	145.60 FL	*- FL
61	1		*REAR FENDER SHIELD LH	Not Necessary	203.98 FL	*- FL
62	1		*REAR FENDER SHIELD RH	Not Necessary	203.98 FL	*- FL
63	1		*SPARE TYRE	Not Necessary	399.70 FL	*- FL
64	1		*SPARE TYRE LOCK	Not Necessary	325.10 FL	*- FL
65	1		*EXHAUST SILENCER BOX	Repair	1,117.48 FL	*- FL
66	3		*EXHAUST MOUNTING	Not Necessary	136.80 FL	*- FL
67	1		*EXHAUST ALUMINIUM BOARD	Not Necessary	155.30 FL	*- FL
68	1		*EXHAUST CENTER PIPE	Not Necessary	893.67 FL	*- FL
69	1		*SET REAR NO PLATE	Bent	65.00 FS	*40.00 FS
70	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
71	1		*SET TAILGATE GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
72	1		*TAILGATE REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
73	1		*SET TAILGATE INNER BOARD CLIPS	Necessary	60.00 FS	*40.00 FS
74	2		*TAIL LAMP CLIPS	Not Necessary	100.00 FS	*- FS
75	2		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
76	1		*SET REAR BUMPER REVERSE SENSOR (2 PCS)	Shorted	350.00 FS	*200.00 FS
77	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
78	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
79	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
80	1		*REAR WELL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
81	2		*REAR FENDER SEALANT	Not Necessary	240.00 FS	*- FS
82	2		*SET REAR FENDER INNER BOARD CLIPS	Not Necessary	120.00 FS	*- FS
83	1		*REAR EXHAUST GASKET	Not Necessary	60.00 FS	*- FS
84	1		*BONNET	Buckled	1,463.29 FL	*1,463.29 FL
85	1		*BONNET LOGO	Necessary	92.80 FL	*92.80 FL
86	1		*BONNET HINGE LH	Bent	132.98 FL	*132.98 FL
87	1		*BONNET HINGE RH	Bent	132.98 FL	*132.98 FL
88	2		*BONNET STOPPER	Not Necessary	45.96 FL	*- FL
89	1		*BONNET INNER MAT	Not Necessary	222.90 FL	*- FL
90	1		*BONNET LOCK	Twisted	278.68 FL	*278.68 FL
91	1		*HEADLAMP LH	Holder Cracked	1,161.90 FL	*1,161.90 FL
92	1		*HEADLAMP RH	Holder Cracked	1,161.90 FL	*1,161.90 FL
93	1		*HEADLAMP TOP PANEL LH	Repair	192.34 FL	*- FL
94	1		*HEADLAMP TOP PANEL RH	Repair	192.34 FL	*- FL
95	1		*GRILLE	Cracked	261.25 FL	*261.25 FL
96	1		*GRILLE CHROME	Scratched	142.60 FL	*142.60 FL
97	1		*WIPER GRILLE	Not Necessary	1,098.50 FL	*- FL
98	1		*WIPER GRILLE COVER LH	Not Necessary	123.40 FL	*- FL
99	1		*WIPER GRILLE COVER RH	Not Necessary	123.40 FL	*- FL
100	1		*FRONT BUMPER	Distorted	647.88 FL	*647.88 FL
101	1		*FRONT BUMPER FOG LAMP LH	Cracked	455.30 FL	*395.00 FL
102	1		*FRONT BUMPER FOG LAMP RH	Cracked	455.30 FL	*395.00 FL
103	1		*FRONT BUMPER FOG LAMP COVER LH	Twisted	159.70 FL	*159.70 FL
104	1		*FRONT BUMPER FOG LAMP COVER RH	Twisted	159.70 FL	*159.70 FL
105	1		*FRONT BUMPER LOWER COVER	Twisted	184.90 FL	*184.90 FL
106	1		*FRONT BUMPER SPONGE	Torn	135.78 FL	*135.78 FL
107	1		*FRONT BUMPER SIDE RETAINER LH	Bent	62.98 FL	*62.98 FL
108	1		*FRONT BUMPER SIDE RETAINER RH	Bent	62.98 FL	*62.98 FL
109	1		*FRONT BUMPER REINFORCEMENT	Bent	375.40 FL	*375.40 FL
110	1		*FRONT FENDER LH	Buckled	598.90 FL	*598.90 FL
111	1		*FRONT FENDER RH	Repair	598.90 FL	*- FL
112	1		*FRONT FENDER SHIELD LH	Not Necessary	198.20 FL	*- FL
113	1		*FRONT FENDER SHIELD RH	Not Necessary	198.20 FL	*- FL
114	1		*FRONT FENDER BRACKET LH	Not Necessary	98.50 FL	*- FL
115	1		*FRONT FENDER BRACKET RH	Not Necessary	98.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*SUPPORT PANEL	Bent	1,617.50 FL	*1,128.10 FL
117	1		*SUPPORT PANEL TOP COVER	Not Necessary	240.20 FL	*- FL
118	1		*BRACE PANEL	Bent	118.78 FL	*118.78 FL
119	1		*HORN LH	Not Necessary	240.60 FL	*- FL
120	1		*HORN RH	Not Necessary	240.60 FL	*- FL
121	1		*AIRCON CONDENSOR	Bent / Punctured	1,591.60 FL	*1,591.60 FL
122	1		*AIRCON CONDENSOR GUIDE LH	Deformed / Torn	198.60 FL	*198.60 FL
123	1		*AIRCON CONDENSOR GUIDE RH	Deformed / Torn	198.60 FL	*198.60 FL
124	1		*AIRCON FAN MOTOR	Not Necessary	687.45 FL	*- FL
125	1		*AIRCON FAN BLADE	Not Necessary	289.20 FL	*- FL
126	1		*AIRCON SUCTION PIPE	Not Necessary	1,481.77 FL	*- FL
127	1		*AIRCON PRESSURE PIPE	Not Necessary	1,698.60 FL	*- FL
128	1		*AIRCON TEMPERATURE SENSOR	Not Necessary	219.40 FL	*- FL
129	1		*RADIATOR	Bent / Punctured	1,806.70 FL	*1,806.70 FL
130	1		*RADIATOR TOP COVER	Not Necessary	310.93 FL	*- FL
131	1		*RADIATOR FAN COWLING }	Cracked	1,210.45 FL	*1,210.45 FL
132	1		*RADIATOR FAN MOTOR }		687.45 FL	*- FL
133	1		*RADIATOR FAN BLADE }		289.20 FL	*- FL
134	1		*RADIATOR TOP HOSE	Not Necessary	248.20 FL	*- FL
135	1		*RADIATOR LOWER HOSE	Not Necessary	268.20 FL	*- FL
136	1		*SET FRONT NO PLATE	Not Necessary	65.00 FS	*- FS
137	1		*SET BONNET INNER MAT CLIPS	Not Necessary	60.00 FS	*- FS
138	1		*SET GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
139	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
140	2		*SET FRONT FENDER SHIELD CLIPS	Not Necessary	120.00 FS	*- FS
141	1		*SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
142	1		*SET SUPPORT PANEL COVER CLIPS	Not Necessary	50.00 FS	*- FS
143	1		*SET AIR DUCT CLIPS	Not Necessary	20.00 FS	*- FS
144	1		*AIRCON GAS	Necessary	60.00 FS	*40.00 FS
145	1		*RADIATOR COOLANT	Necessary	120.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	54,456.48	21,150.99
- List Item Discount on L Items 25.00/25.00% (\$)	12,941.62	5,152.75
Total Parts (\$)	41,514.86	15,998.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO PANEL BEAT /CUT /WELD AFFECTED PANELS ,REALIGN AND REFIT /REPLACE NECESSARY AFFECTED PARTS	New	2,800.00	800.00
2	TO PUTTY AND SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	2,200.00	1,100.00
3	TO REMOVE AND TRANSFER REAR WINDSCREEN TO NEW TAILGATE	New	180.00	120.00
4	TO TRANSFER COMPONENTS TO NEW TAILGATE	New	120.00	60.00
5	TO DISCONNECT /RECONNECT AND CHECK FOR PROPER WIRING AND ELECTRICAL FUNCTION	New	100.00	30.00
6	TO APPLY ANTI RUST COATING	New	120.00	60.00
7	TO REMOVE AND TRANSFER REAR FENDER GLASS TO NEW FENDER	New	240.00	0.00
8	TO REMOVE AND REINSTALL REAR COMPARTMENT TRIMS	New	100.00	80.00
9	TO REMOVE AND REPLACE EXHAUST SYSTEM	New	250.00	60.00
10	TO DIAGNOSTIC RESET FAULT CODE BACK TO MANUFACTORY SETTING	New	450.00	0.00
11	TO DISMANTLE AND REINSTALL PETROL TANK FOR REPLACE REAR WELL PANEL	New	350.00	0.00
12	TO DISMANTLE AND REPLACE REAR BUMPER REVERSE SENSOR WITH DISTANCE TEST	New	100.00	50.00
13	TO DISMANTLE AND REINSTALL REAR PASSENGER SEAT FOR REPLACE REAR WELL PANEL	New	280.00	0.00
14	TO CHECK WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
15	LABOUR TO PANEL BEAT /CUT /WELD AFFECTED PANELS ,REALIGN AND REFIT /REPLACE NECESSARY AFFECTED PARTS	New	2,200.00	800.00
16	TO PUTTY AND SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	1,800.00	1,000.00
17	TO DISCONNECT /RECONNECT AND CHECK FOR PROPER WIRING AND ELECTRICAL FUNCTION	New	100.00	0.00
18	TO APPLY ANTI RUST COATING	New	120.00	80.00
19	TO DISMANTLE AND REINSTALL RADIATOR WITH HIGH PRESSURE TEST }	New	120.00	100.00
20	TO DISMANTLE AND REINSTALL AIRCON CONDENSOR WITH TOP UP GAS }	New	120.00	0.00
Gross Labour Cost (S\$)			11,830.00	4,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >