



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 9261K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	1,011.00	762.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	89.00	-
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	89.00	-
1	FRONT BUMPER SIDE GARNISH LH	GRAZED	140.00	140.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	549.00	-
1	FRONT BUMPER FOG LAMP COVER LH	NOT NECESSARY	178.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	589.00	-
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	115.00	-
1	FRONT FENDER SIDE GARNISH LH	GRAZED	241.00	180.00
1	FRONT WHEEL BEARING LH	DAMAGED	359.00	359.00
1	FRONT KNUCKLE ARM LH	BENT	289.00	289.00
1	FRONT LOWER ARM LH	BENT	289.00	289.00
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	875.00	-
	LESS 20% DISCOUNT		-962.60	-403.80
			3,850.40	1,615.20
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	50.00	-
1	FRONT TYRE RH (SN)	SERVICEABLE	280.00	-
1	FRONT RIM RH (SN)	WARPED	890.00	480.00
1	JOINT SEALANT (SN)	NOT NECESSARY	120.00	-
			1,390.00	530.00
	<u>LABOUR</u>			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		100.00	20.00
	REMOVE AND REFIT FRONT LINING, TRIM AND GARNISH.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		1,000.00	320.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	400.00

Report Ref No. CS/SMR22010860/Uny3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
			2,350.00	740.00
GRAND TOTAL			7,590.40	2,885.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/SMR22010860/Uny3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.