

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT UNITED OVERSEAS INSURANCE LTD CS3/UOI22010863/Gvy3m4 Ref: 146 ROBINSON ROAD Date: 10/11/2022 #02-01 UOI BUILDINGSINGAPORE 068909 Code: UOI2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLT 6988M** GBJ 3940R Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. M11D00042211 Excess (\$) 0.00 LEE KATIE **Assign Date** 01/11/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE Make & Model 2982 c.c 2019 HIDDEN Engine No. Year of Reg. JTFHT02P500248398 WHITE Chassis No. Colour Odometer 141450 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15 BRIDGESTONE 6 mm L/H Front Tyre 195 R15 BRIDGESTONE 6 mm 195 R15 BRIDGESTONE R/H Rear Tyre 6 mm **BRIDGESTONE** L/H Rear Tyre 195 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 16/10/2022 07/11/2022 (03:00 PM) Inspect Date / Time Accident Date JL AUTO SERVICES PTE LTD Survey held at BLK 3006 UBI ROAD 1 #01-346 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/UOI22010863/Gvy3m4

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days

Automotive Assessor