

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8868R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT CABIN ASSY (WCP)	BENT	10,500.00	10,500.00
1	DASHBOARD ASSY (WCP) }	BROKEN	7,500.00	7,500.00
1	DASHBOARD REINFORCEMENT (WCP) }		-	-
1	AIR CON BLOWER (WCP) }		-	-
1	AIR CON COOLING COIL (WCP) }		-	-
1	AIR CON HEATER UNIT (WCP) }		-	-
4	DASHBOARD LOURVE (WCP) }		-	-
1	DASHBOARD LOURVE INNER DUCT (WCP) }		-	-
1	DASHBOARD METER (WCP) }		-	-
1	CABIN SEATS ASSY (WCP) }		-	-
1	STEERING WHEEL (WCP) }		-	-
1	STEERING WHEEL COVER - (TOP/LOWER) (WCP) }		-	-
1	STEERING COLUMU (WCP) }		-	-
1	STEERING COLUMU SHAFT (WCP) }		-	-
1	STEERING COLUMU CONE (WCP) }		-	-
1	SIGNAL / WIPER HAND INDICATOR (WCP) }		-	-
1	STEERING BOX (WCP)	JAMMED	3,200.00	3,200.00
1	WOODEN FLATBED PARTITION (WCP)	CRACKED	3,500.00	3,500.00
	COST PLUS 15%		3,705.00	3,705.00
			28,405.00	28,405.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE / REPLACE ABOVE PARTS AND RE-ALIGN AFFECTED PORTION.		4,000.00	3,200.00
	TO PUTTY AND RESPRAY AFFECTED PORTION.		1,800.00	1,500.00
	CHASSIS ALIGNMENT.		1,200.00	1,000.00
	WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			7,080.00	5,700.00
	GRAND TOTAL		35,485.00	34,105.00

Report Ref No. CS/LPC22010866/Kvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		27,000.00
LESS EXCESS		-700.00
NETT LIABILITY		26,300.00

Report Ref No. CS/LPC22010866/Kvy3e2

KONG SENG CHEONG

**Licensed Appraiser**