12/2/22, 6:08 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS3/CTI22010868/SWP3M4 Our File No:

02/12/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

Policy No: DMPCSNW00155682200 (Singapore) Pte. Ltd.

Claimant Vehicle No:

SKZ9094C

No:

Insured Vehicle SJJ2751G

Claim SNM22D207723/C02/IRENE Date of Loss: 27/10/2022 Nature of Claim: TP

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKZ9094C Reg No:

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4028821 Reg. Date: 15/02/2016 (Man. Year: 2015) Chassis No: RU11108816 Colour: Black Odometer: 75672 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Farroad 5 mm Rear Left Side: Farroad 6 mm Front Right Side: Rear Right Side: Farroad 6 mm Farroad 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/11/2022

WEE HOE AUTO SERVICE Date Inspected: 01/11/2022 Inspected At: 19 KIM CHUAN TERRACE

SINGAPORE 537041

Estimated Period of Repair: 4.0 days

S Mohamed Irfan Bin Mohamed Iqubal Adjuster: Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/2/22, 6:08 PM Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

12/2/22, 6:08 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Dec 2022)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ9094C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

12/2/22, 6:08 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >