

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22010870/AYA3Q2**Date:** 15/06/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0008814
Claimant Vehicle No :	SJL4855S	Insured Vehicle No :	SLG2594K
Date of Loss:	01/11/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0007221

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL4855S	Engine No:	3SZ2221948
Make & Model:	TOYOTA RUSH, 1.5 X (A)	Chassis No:	J200E0024688
Reg. Date:	28/11/2008 (Man. Year: 2008)	Odometer:	336281 km
Colour:	Red		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,144.15	4,547.50	4,596.65	50.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,870.00	1,180.00	38.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,194.15	6,417.50	5,776.65	47.37
Approved Total (Overridden) (\$\$)		5,100.00		
(\$\$)	12,194.15	5,100.00	7,094.15	58.18
+ GST 8.00/8.00% (\$\$)	975.53	408.00	567.53	58.18
Nett Amount (\$\$)	13,169.68	5,508.00	7,661.68	58.18
+ Loss of Use (8.0 x S\$60.00/day) (\$\$)		480.00		
+ Doc/Search Fee (\$\$)		38.45		
Nett Liability (\$\$)		6,026.45		
Global Sum Settlement (\$\$)		6,000.00		

INSPECTION

Date of Assignment:	01/11/2022	
Date Inspected:	02/11/2022	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL4855S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	796.00 FL	*796.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
3	1		*REAR BUMPER O/S TOW COVER	Missing	50.00 FL	*50.00 FL
4	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	343.80 FL	*150.00 FL
5	2		*REAR BUMPER O/S & N/S BUMPER REFLECTOR	Not Necessary	256.20 FL	*- FL
6	1		*REAR SPARE WHEEL COVER	Cracked	1,380.00 FL	*1,380.00 FL
7	1		*REAR SPARE WHEEL BASE COVER	Cracked	1,520.00 FL	*435.00 FL
8	1		*REAR SPARE WHEEL BRACKET	Not Necessary	790.00 FL	*- FL
9	2		*REAR SPARE WHEEL COVER LOCK	Not Necessary	60.00 FL	*- FL
10	1		*REAR TAILGATE	Dented	1,680.00 FL	*1,404.00 FL
11	1		*REAR TAIL GATE WEATHERSTRIP	Cut	520.00 FL	*259.00 FL
12	1		*REAR TAILGATE RUSH EMBLEM	Necessary	67.00 FL	*67.00 FL
13	2		*REAR TAILGATE HINGES	Not Necessary	296.00 FL	*- FL
14	1		*REAR TAIL GATE LOCK	Damaged	206.00 FL	*206.00 FL
15	1		*REAR TAIL GATE LOCK CATCH	Not Necessary	70.00 FL	*- FL
16	1		*REAR TAIL GATE LOCK HANDLE (OUTER)	Not Necessary	287.00 FL	*- FL
17	1		*REAR TAIL GATE INNER TRIM	Cracked	490.00 FL	*362.00 FL
18	12		*REAR TAIL GATE INNER TRIM CLIPS	Necessary	144.00 FL	*30.00 FL
19	2		*REAR O/S & N/S TAIL LAMP	Not Necessary	960.00 FL	*- FL
20	1		*REAR TAIL GATE END PANEL	Dented	978.20 FL	*481.00 FL
21	1		*REAR TAIL GATE END PANEL INNER TRIM	Cracked	320.00 FL	*198.00 FL
22	5		*REAR TAIL GATE END PANEL INNER TRIM CLIPS	Necessary	60.00 FL	*20.00 FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
24	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
25	1		*REAR REG NO PLATE	Bent	45.00 FS	*30.00 FS
26	1		*REAR REG NO PLATE BRACKET	Deformed	29.00 FS	*29.00 FS
27	2		*REAR REG NO PLATE LAMP	Not Necessary	206.00 FL	*- FL
28	2		*REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,014.20	6,007.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,870.05	1,459.50
Total Parts (\$\$)	9,144.15	4,547.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE REAR PORTION ,STRAIGHTEN & WELDING	New	1,400.00	800.00
2	TO SPRAY PAINTING	New	1,200.00	800.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	80.00	0.00
4	TO REMOVE & REPLACE REAR WINDSCREEN	New	140.00	120.00
5	TO REMOVE & REPLACE REAR TAIL GATE FITTINGS	New	100.00	60.00
6	TO CHECK WIRING	New	50.00	30.00
7	TO RE SEAL ANTI RUST	New	80.00	60.00
Gross Labour Cost (\$\$)			3,050.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >