

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP 111

Xiao Tony

J200E 0024688

ESTIMATE OF REPAIR

Veh# SJL4855S

Model: TOYOTA RUSH

Accident Date : 1/11/2022

28/11/2008-27/11/2023

Location : CTE (CITY) NEAR ANG MO KIO

3P: SLG2594K (III)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Defect</i>	796.00	✓	
2	10 pcs	Rear bumper clips <i>Ne</i>		40.00	✓
3	1 pc	Rear bumper o/s tow cover <i>Missing</i>	50.00	✓	
4	2pcs	Rear bumper o/s & n/s retainer <i>Ne</i>	343.80	✓	150
5	2pcs	Rear bumper o/s & n/s bumper reflector <i>Ne n</i>	256.20	+	
6	1 pc	Rear spare wheel cover <i>Cracked</i>	380.00	✓	
7	1 pc	Rear spare wheel base cover <i>Cracked</i>	520.00	✓	435
8	1 pc	Rear spare wheel bracket <i>Ne n</i>	790.00	+	
9	2 pcs	Rear spare wheel cover lock <i>Ne n</i>	60.00	+	
10	1 pc	Rear tail gate <i>Defect</i>	1,680.00	✓	1404
11	1 pc	Rear tail gate weatherstrip <i>Cr</i>	520.00	✓	259
12	1 pc	Rear tail gate Rush emblem <i>Ne n</i>	67.00	✓	
13	2 pcs	Rear tail gate hinges <i>Ne n</i>	296.00	✓	
14	1 pc	Rear tail gate lock <i>Defect</i>	206.00	✓	
15	1 pc	Rear tail gate lock catch <i>Ne n</i>	70.00	+	
16	1 pc	Rear tail gate lock handle (Outer) <i>Ne n</i>	287.00	+	
17	1 pc	Rear tail gate inner trim <i>Cracked</i>	490.00	✓	362
18	12 pcs	Rear tail gate inner trim clips <i>Ne</i>	144.00	✓	30
19	2 pcs	Rear o/s & n/s tail lamp <i>Ne n</i>	960.00	+	
20	1 pc	Rear tail gate end panel <i>Defect</i>	978.20	✓	481
21	1 pc	Rear tail gate end panel inner trim <i>Cracked</i>	320.00	✓	198
22	5 pcs	Rear tail gate end panel inner trim clips <i>Ne n</i>	60.00	✓	20
23	1 pc	Rear windscreen sealant <i>Ne</i>		80.00	40
24	1 pc	Rear windscreen inner seal <i>Ne</i>		60.00	30
25	1 pc	Rear reg. no. plate <i>Best</i>		45.00	30
26	1 pc	Rear reg. no. plate bracket <i>Defect</i>		29.00	✓
27	2 pcs	Rear reg. no. plate lamp <i>Ne n</i>	206.00	+	
28	2 pcs	Rear reverse sensor <i>Ne n</i>		280.00	+
Sub Total:			10,980.20	534.00	0.00
			25%	0%	10%
After Less %:			8235.15	534.00	0.00
Labour					
1		To dismantle rear portion, straighten & welding.	1,400.00	✓	800
2		To spray painting.	1,200.00	✓	800
3		To remove & replace rear reverse sensor.	80.00	+	
4		To remove & replace rear windscreen.	440.00	✓	120
5		To remove & replace rear tail gate. <i>Fittings</i>	100.00	✓	60
6		To check wiring.	50.00	✓	30
7		To re seal anti rust.	80.00	✓	60
Sub Total:			3,050.00		
Total:			11819.15		
After Less 20%:			9455.32		

5838

4378.57

S.N: 169

Admin Lj
w/s 02/11/22.

06 Days

Total: 6417.57

h/s: 5.1K

Chan San Choon
Director
DipEng, AAE, MIM, MSAE (Aus)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJL4855S ESTIMATEPg1

