

ASS. REC. BY:

REF: ASM/ 220108731kyp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 GNA & EM not ready

10/3 6/1 Pm @ 11,800 Cahr

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

PNG 8340M Yr Regn: 09, 16

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ B180

Engine/Chassis No.: WDD2462422J403892

Date of accident:


Damaged area: Front & Rear

Date: 01/11/2022

Claim Type: TP

VRN: SNG8340M

Not Authorized
 11 Lmp & 11, 800/hr
 Recovery After Painting
 7 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tailgate	1	\$ 1,841.00	\$ 1,841.00	✓
2	Tailgate hinge	2	\$ 184.00	\$ 368.00	X
3	Tailgate lift absorber	2	\$ 221.00	\$ 442.00	X
4	Tailgate lock	1	\$ 386.00	\$ 386.00	X
5	Tailgate lock striker	1	\$ 82.00	\$ 82.00	X
6	Tailgate lock striker cover	1	\$ 65.00	\$ 65.00	X
7	Tailgate lamp	2	\$ 643.00	\$ 1,286.00	X
8	Tailgate centre chrome garnish	1	\$ 365.00	\$ 365.00	X
9	Tailgate "MERCEDES BENZ STAR" emblem	1	\$ 97.00	\$ 97.00	✓
10	Tailgate "B180" emblem	1	\$ 76.00	\$ 76.00	✓
11	Tailgate "C&C" emblem	1	\$ 98.00	\$ 98.00	✓
12	Tailgate inner trim	1	\$ 411.00	\$ 411.00	X
13	Tailgate licence plate lamp	2	\$ 153.00	\$ 306.00	X
14	Rear bumper	1	\$ 1,318.00	\$ 1,318.00	✓
15	Rear bumper lower panel	1	\$ 603.00	\$ 603.00	✓
16	Rear bumper lower panel chrome moulding	1	\$ 236.00	\$ 236.00	✓
17	Rear bumper tow cover	1	\$ 45.00	\$ 45.00	X
18	Rear bumper side retainer	2	\$ 136.00	\$ 272.00	X
19	Rear bumper reinforcement <i>SSS</i>	1	\$ 790.00	\$ 790.00	✓
20	Rear bumper reinforcement bracket	2	\$ 349.00	\$ 698.00	X
21	Rear bumper lower guide bracket	2	\$ 177.00	\$ 354.00	X
22	Rear bumper inner bracket	1	\$ 391.00	\$ 391.00	X
23	Rear bumper upper mount bracket	4	\$ 62.00	\$ 248.00	X
24	Taillamp	2	\$ 898.00	\$ 1,796.00	X
25	Taillamp lower bracket	2	\$ 85.00	\$ 170.00	X
26	Taillamp side garnish	2	\$ 79.00	\$ 158.00	X
27	Tailgate licence plate lamp garnish	1	\$ 137.00	\$ 137.00	X
28	Tailgate weatherstrip	1	\$ 189.00	\$ 189.00	X
29	Rear bumper chrome protector	1	\$ 398.00	\$ 398.00	✓
30	End panel	1	\$ 719.00	\$ 719.00	X
31	End panel top garnish	1	\$ 372.00	\$ 372.00	X
32	Spare tyre floor panel	1	\$ 883.00	\$ 883.00	X
33	Spare tyre top board	1	\$ 365.00	\$ 365.00	X
34	Bonnet	1	\$ 1,520.00	\$ 1,520.00	X

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

35	Bonnet hinge	R	2	\$ 211.00	\$ 422.00	X
36	Bonnet logo	Sm	1	\$ 99.00	\$ 99.00	X
37	Bonnet spring	Sm	2	\$ 85.00	\$ 170.00	X
38	Bonnet actuator	Sm	2	\$ 375.00	\$ 750.00	X
39	Bonnet lock lever	Sm	1	\$ 85.00	\$ 85.00	X
40	Front bumper	1360.40 CMT	1	\$ 1,452.00	\$ 1,452.00	✓
41	Front bumper reinforcement	R	1	\$ 756.00	\$ 756.00	X
42	Front bumper reinforcement bracket	R	2	\$ 276.00	\$ 552.00	X
43	Front bumper sponge	CMT	3	\$ 175.00	\$ 525.00	✓
44	Front bumper retainer	Sm	2	\$ 194.00	\$ 388.00	X
45	Front grille	640.20 CMT	1	\$ 940.00	\$ 940.00	✓
46	Front grille logo	Sm	1	\$ 98.00	\$ 98.00	✓
47	Front bumper lower grille	Sm	1	\$ 445.00	\$ 445.00	X
48	Headlamp	22340 M3 CMT	2	\$ 2,372.00	\$ 4,744.00	✓
49	Headlamp panel	R	2	\$ 294.00	\$ 588.00	X
50	Headlamp garnish	Sm	2	\$ 173.00	\$ 346.00	X
51	Support panel center	Sm	1	\$ 514.00	\$ 514.00	X
52	Support panel center top garnish	Sm	1	\$ 332.00	\$ 332.00	X
53	Front bumper tow hook cover	Sm	1	\$ 93.00	\$ 93.00	X
54	Front bumper lower chrome moulding	Sm	1	\$ 364.00	\$ 364.00	X
55	Front grille inner bracket	Sm	1	\$ 98.00	\$ 98.00	X
Subtotal				\$ 31,246.00		
List discount				10.00%		
Total				\$ 28,121.40		

Special nett items					
No.	Parts description		QTY	UNIT PRICE	AMOUNT
1	Tailgate centre chrome garnish clips	nn	6	\$ 5.50	\$ 33.00
2	Tailgate inner trim clips	nn	14	\$ 5.50	\$ 77.00
3	Rear bumper clips	nn	12	\$ 5.50	\$ 66.00
4	Rear bumper sensor C236	sh47	42	\$ 280.00	\$ 1,120.00
5	Rear bumper sensor holder	nn	42	\$ 67.00	\$ 268.00
6	Rear bumper sensor harness	sh	1	\$ 783.00	\$ 783.00
7	End panel sealant	nn	1	\$ 120.00	\$ 120.00
8	End panel top garnish clips	nn	6	\$ 5.50	\$ 33.00
9	Spare tyre floor panel sealant	nn	1	\$ 120.00	\$ 120.00
10	Rear licence plate & frame	sh	1	\$ 55.00	\$ 55.00
11	Bonnet insulator clips	nn	10	\$ 5.50	\$ 55.00
12	Front bumper sensor	sh	2	\$ 280.00	\$ 560.00
13	Front bumper sensor holder	sh	2	\$ 22.00	\$ 44.00
14	Front bumper clips	nn	12	\$ 5.50	\$ 66.00
15	Front licence plate & frame	sh	1	\$ 55.00	\$ 55.00
16	Support panel center top garnish clips	nn	6	\$ 5.50	\$ 33.00
17	Front bumper lower lip	sh	1	\$ 800.00	\$ 800.00
18	Rear bumper lower lip	sh	1	\$ 800.00	\$ 800.00
19	Sundries	nn	1	\$ 50.00	\$ 50.00
Total					\$ 5,138.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	11	\$ 2,200.00
2	To disconnect front & rear wire harness of electrical components to facilitate repairs, reconnect and check functions including headlamp / taillamp lightings.	0.5	\$ 100.00
3	To remove, refit tailgate components and replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	10	\$ 2,000.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 4,500.00
Estimate Grand Total			\$ 37,759.40

8001

401

601

8801

301

10,000.00

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ B180

Engine/Chassis No.: WDD2462422J403892


Date of accident:

Damaged area: Front & Rear

Date: 01/11/2022

Claim Type: TP

VRN: SNG8340M



Supplementary list items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front distance radar	1	\$ 1,541.00	\$ 1,541.00
2	Exhaust heatshield	1	\$ 399.00	\$ 399.00
3	Front licence plate base	1	\$ 194.00	\$ 194.00
Subtotal				\$ 2,134.00
List discount				10.00%
Total				\$ 1,920.60

Supplementary Estimate Grand Total	\$ 1,920.60
------------------------------------	-------------