

### PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Abdul Rashid

<b>Assign Date:</b>	05/07/2021	<b>Survey Date:</b>	06/07/2021	<b>Adjustment Date:</b>	03/01/2022
<b>Accident Date:</b>	16/06/2021	<b>TP Policy No:</b>	5109046349-02	<b>Our Ref:</b>	AVS2021-27859/BL
<b>Place of Survey:</b>	H L Cycle Pte Ltd 1 Kaki Bukit Avenue 6 #02-58 Autobay Singapore 417883			<b>Your Ref:</b>	MT/1134988-002
				<b>Claim Type:</b>	Third Party
				<b>Claimant:</b>	Nur Hartani Binte Haron

#### Description of Vehicle:

<b>Veh. No:</b>	FBP5085P	<b>Make/Model:</b>	Yamaha Sniper	<b>Sum Insured (S\$):</b>	Market Value
<b>Colour:</b>	Black	<b>Engine No:</b>	G3E6E0484957	<b>Mkt Value (S\$):</b>	\$8,700.00
<b>Engine Capacity:</b>	150 cc	<b>Chassis No:</b>	MH3UG0740K0152800	<b>Excess (S\$):</b>	NA
<b>Odometer:</b>	NA	<b>Reg. Date:</b>	24/04/2019		

#### Condition of Vehicle:


<b>General:</b>	Fair	<b>Modification:</b>	No	<b>Steering:</b>	Affected
<b>Handbrake:</b>	Affected	<b>Footbrake:</b>	Affected	<b>Paint work:</b>	Fair
<b>Tyre Make:</b>	Maxxis				
<b>Front Tyre Size:</b>	100/80R17	<b>Front Side:</b>	4mm		
<b>Rear Tyre Size:</b>	100/80R17	<b>Rear Side:</b>	4mm		

#### Description of Damage:

The vehicle sustained damage on the front, left and right portions.

#### Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$4,300.00 with approximately three (3) working days to complete. However, no finalisation was agreed with the repairer.

  
**Adjuster:** Billy Loh  
 Motor Appraiser

COMPLETED 13 JAN 2022

Date

**Note:** This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

**Adjustment of Repair Cost for Vehicle:**

**FBP5085P**

**Our Ref:** AVS2021-27859/BL

No.	Qty	Description of Parts	Condition	Third Party Survey Report S\$	Our Recommendation S\$
<b>List Items</b>					
1	2	Front fork tube assy	Bent	880.00	880.00
2	1 set	Wheel rim	Repair	800.00	--
3	1	Fork under bracket	Bent	185.00	185.00
4	1	Front rim shaft	Bent	45.00	45.00
5	1	Front rim bearing	Bent	38.00	38.00
6	1	Front brake disc	Not necessary	155.00	--
7	1	Handle bar	Bent	88.00	88.00
8	1	N/s handle bar end	Dented	32.00	32.00
9	1 set	Handle grip	Cut	55.00	55.00
10	1	Side mirror	Cut	55.00	55.00
11	1	Front signal	Cracked	90.00	90.00
12	1	Headlamp	Cracked	185.00	185.00
13	1	Meter assy	No photo	385.00	--
14	1 set	Fairing assy	Cracked	750.00	750.00
15	1	Radiator	Dented	458.00	458.00
16	1	Radiator tank	Dented	78.00	78.00
17	1	Front footrest bracket	Dented	65.00	65.00
18	2	Front footrest rubbers	Dented	70.00	70.00
19	1	Gear pedal	Bent	42.00	42.00
20	1	Brake pedal	Bent	42.00	42.00
21	1	Rear n/s footrest	Bent	40.00	40.00
22	1	Rear n/s footrest bracket	Bent	78.00	78.00
23	1	Exhaust assy	Dented	485.00	485.00
24	1	Exhaust protector - front	Dented	60.00	60.00
25	1	Exhaust protector - rear	Dented	70.00	70.00
26	1	Exhaust pipe end cover	Dented	58.00	58.00
27	1	Kick starter	Dented	--	--
28	1	Main stand	Dented	--	--
29	1	Rear fender	Cracked	120.00	120.00
30	2	Rear signals	Cracked	136.00	136.00
31	1	Basket	Cracked	50.00	50.00

**Note:** This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

### Adjustment of Repair Cost for Vehicle:

**FBP5085P**

**Our Ref:** AVS2021-27859/BL

No.	Qty	Description of Parts	Condition	Third Party Survey Report S\$	Our Recommendation S\$
32	1	Swing arm	Bent	425.00	425.00
<b>Sub Total:</b>				6,020.00	4,680.00
<b>Discount (less 10% ):</b>				<b>602.00</b>	<b>468.00</b>
				5,418.00	4,212.00

### Special Nett Items

1	1 set	Number plate	Necessary	28.00	15.00
2	2	Fork oil	Necessary	30.00	30.00
3	2	Fork oil seals	Necessary	56.00	56.00
4	1	Rear box	Dented	280.00	200.00
5	1	Rear box bracket	Bent	100.00	100.00
6	1	Swing arm rubber	Bent	75.00	75.00
7	1	Front tyre (Depreciation)	No photo	75.00	--
8	1	Rear tyre (Depreciation)	No photo	75.00	--
9	1	Coolant	Necessary	18.00	18.00
10	1	ERP IU	Dented	175.00	175.00
11	1 set	Sticker	Necessary	95.00	95.00
<b>Sub Total:</b>				1,007.00	764.00
<b>Total Parts Price:</b>				6,425.00	4,976.00

### Labour Cost

1	To provide towing servide.	50.00	--
2	To check electrical system, wire harness and focus headlamp.	50.00	20.00
3	To provide labour charges, workmanship to dismantle abvoe damaged parts; re-align body structure and damaged consistent to the accident.	400.00	250.00
4	To check, repair and striaghten body frame to the original position.	350.00	150.00
<b>Sub Total:</b>		850.00	420.00
<b>Grand Total:</b>		7,275.00	5,396.00

**Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.**

**AJAX Inspection Services Pte Ltd**

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website:www.ajaxadjusters.com Co. Reg. No.: 201318067R