

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

# **INVOICE**

Invoice No.:

CL/210388

Nur Haryani Binte Haron

C/o: H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

Ref No.:

HLC/07/2101/TP

Date:

4 August 2021

	DESCRIPTION		AMOUNT
OUR SERVICE FE	E CHARGES:		
• SURVEY	INSPECTION FOR VEHICLE NO.	<u>FBP 5085 P</u>	
• RESURVI	EY INSPECTION		
	PHOTOGRAPHS SERVICES  STORAGE AND SUBMISSION OF DIGITAL I	PHOTOGRAPHS)	
• TRANSPO	ORTATION		
		GRAND TOTAL	S\$ 653.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CLAPPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.

CL Appraiser Pte Ltd

24 Penshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Nur Haryani Binte Haron

C/o: H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

: 16 June 2021

Inspection Date :

: 07 July 2021

Repairer Name

Accident Date

: H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

PARTICULARS OF VEHICLE

Registration No : 1

: FBP 5085 P

Year / Capacity:

Type of Survey: Third Party

2019 / 150 cc

: 4 August 2021

: HLC/07/2101/TP

Make / Model

: Yamaha Sniper

Colour

Date

Our ref

0

Chassis No

: MH3UG0740K0152800

Mileage

Grey

Engine No

: G3E6E0484957

**CONDITION OF TYRES** 

Make

Size

**Thread Balance** 

Rim

Front

Pirelli

90/80 -17

5 mm

Sport

Rear

Maxxis

100/80 -17

5 mm

Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s and n/s portion.

(Details refer to the photographs attached)

Enclosed number of photographs:

173

copies

#### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

#### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$5,800.00 on a contractual basis.

Under normal circumstances, the repair period would be about 15 (Fifteen) working days.



Vehicle Registration No.: FBP 5085 P Our Ref No.: HLC/07/2101/TP

Qty	Qty Description		Conditions		Repairer's Estimate		Revised Amount		
	SPARE PARTS - LIST ITEMS								
2	Front fork tube assy	andgeloegiske aterekteen	Damage	\$	880.00	\$	880.00		
1	Wheel rim (1 set) X Repair		Damage	\$	800.00	\$	800.0		
1	Fork under bracket		Damage	.\$	185.00	\$	185.0		
1	Front rim shaft		Necessary	\$	45.00	\$	45.0		
1	Front rim bearing		Necessary	\$	38.00	\$	38.0		
1	Front brake disc X SVC		Damage	\$	155.00	\$	155.0		
1	Handle-bar		Damage	\$	88.00	\$	88.00		
1	N/s handle-bar end		Damage	\$	32.00	\$	32,00		
1	Hand grip (1 set)		Necessary	\$	55.00	\$	55.0		
. 1	Side mirror		Damage	\$	55.00	\$	55.0		
1	Front signal		Damage	\$	90.00	\$	90.0		
	Headlamp		Damage	\$	185.00	\$	185.0		
1	Meter assy X SVC	riging malay his empresa e Pages estangag	Damage	\$	385.00	\$	385.0		
1	Fairing assy (1 set )		Damage	\$	750.00	\$	750.0		
1	Radiator		Damage	\$	458.00	\$	458.00		
1	Radiator tank		Damage	\$	78.00	\$	78.0		
1	Front footrest bracket		Damage	\$	65.00	\$	65.0		
2	Front footrest rubbers		Necessary	\$	70.00	\$	70.0		
1	Gear pedal		Damage	\$	42.00	\$	42.00		
1	Brake pedal		Damage	\$	42.00	\$	42.00		
1	Rear n/s footrest		Damage	\$	40.00	\$	40.00		
1	Rear n/s footrest bracket		Damage	\$	78.00	\$	78.00		
1	Exhaust assy		Damage	\$	485.00	\$	485.00		
1	Exhaust protector - front		Damage	\$	60.00	\$	60.00		
	Exhaust protector- rear		Damage	\$	70.00	\$	70.00		
	Exhaust pipe end cover		Damage	\$	58.00	\$	58.00		
	Kick starter	SVC	Intact	\$	85.00	*			
	Main stand	SVC	Intact	\$	95.00				
	Rear fender		Damage	\$	120.00	\$	120.00		
	Rear signals		Damage	\$	136.00	\$	136.0		
	Basket		Damage	\$	50.00	\$	50.00		
	Swing arm		Damage	\$	425.00	\$	425.00		
				\$	6,200.00	\$	6,020.00		
			Less 10%	\$	620.00	\$	602,00		

**Total Cost - List Items** 

5,580.00 \$

5,418.00



Vehicle Registration No.: FBP 5085 P

Our Ref No.: HLC/07/2101/TP

Qty	Description		Conditions		Repairer's Estimate	Revised Amount		
	List Items To		\$	5,580.00	\$	5,418.00		
nata mitya	SPECIAL NETT ITEMS	t o northwest meanan (setual of stage	eo e socialmenta de l'obsentante il socialmente	are despeta	n the Equation (Control of the Control of the Cont	endstelykodiner	onnet villanstein av kansonseta	
1	Number plate (1 set)		Damage	\$	28.00	\$	28,00	
2	Fork oils		Necessary	\$	30.00	\$	30.00	
2	Fork oil seals		Necessary	\$	56.00	\$	56.00	
1	Rear box	at i et ertra i ekirt eletti vätera estargalegedarterka	Damage	\$	280.00	\$	280.00	
1	Rear box bracket		Damage	\$	100.00	\$	100.00	
1	Swing arm rubber		Necessary	\$	75.00	\$	75.00	
1	Front tyre (Depreciation)	X SVC	Damage	\$	150.00	\$	75.00	
1	Rear tyre (Depreciation)	X SVC	Damage	\$	150.00	\$	75.00	
1 🧇	Coolant		Necessary	\$	18.00	\$	18.00	
1	ERP IU		Damage	\$	175.00	\$	175.00	
1	Sticker (1 set)	kamanan aman naganga minan katamangat taguta 20,000 ya minin kanganga 15,550 kilo. Kataman an minin kangan kangan kanan kanan kangan kangan kangan kangan kangan kangan kangan kangan kangan kang	Necessary	\$	95.00	\$	95.00	
	Total Cost - S	\$	1,157.00	\$	1,007.00			

**Total cost of parts** 

\$ 6,737.00	\$ 6,425.00



Vehicle Registration No.: FBP 5085 P

Our Ref No.: HLC/07/2101/TP

	S/No	Description		Repairer's Estimate		Revised Amount	
		Total cost of parts c/f	\$	6,737.00	\$	6,425.00	
o este established a lest a	myre i a i me l'hydystell,	is $\overline{LABOUR}$ and some consequences are produced associated to a consequence and the consequence of the consequence and $x$	See yarta see aengaya	Panal salah milang sapang manal salah	vasti in enepti	ganan gana kantan mengangan ganan kantan s	
	1	To provide towing service.	<b>\$</b> :	50.00	\$	50.00 🗸	
n ny taona kaominina	<u>2</u>	To check electrical system, wire harness and focus headlamp.	\$	80.00	\$	50.00.20	
ľ.	3	To provide labour charges, workmanship to dismantle above damaged parts; re-align body structure and damaged consistent to the accident.	\$	480.00	\$	400.00 🗸	
	4 	To check, repair and straighten body frame to the original position.	\$	350.00	\$	350.00150	
2000 - 1200g	service of a	GRAND TOTAL	<b>\$</b>	7,697.00	<u> </u>	7,275.00	

-20%: 4400

4 Days



Vehicle Registration No.: FBP 5085 P

Our Ref No.:

HLC/07/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 5,800.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser