

You're Ref: TP/IP/27456/2022
Our Ref: CI/TPD22010888/P

14th November 2022

General Investigation Team

Traffic Police Department
Singapore Police Force
10 Ubi Avenue 3
Singapore 408865

MECHANICAL INSPECTION REPORT OF ELECTRIC TAXI SHA 8586Z

1. I refer to your request on 31st October 2022 to conduct a physical inspection of an Electric Taxi bearing registration number SHA 8586Z (herein referred to as "**Electric Taxi**"), which was involved in a road traffic accident on 9 October 2022.
2. The objective of the inspection is to determine if there was any possible mechanical failure to the Electric Taxi that may have contributed to the accident.
3. Following the request, I had carried out a physical inspection of the Electric Taxi on 11th November 2022 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. I now set out below my observations and comments with respect to this inspection.

General Condition


4. The mileage of the Electric Taxi at the time of my inspection was 21,593km.
5. There was no visible damage observed on Electric Taxi at the time of my inspection.

Tyres and Wheel Rims

6. The condition of the Electric Taxi's 4 tyres was observed to be in serviceable condition. I did not find any tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 4 tyres. The 4 tyres were also observed to be sufficiently inflated for vehicular operation. The tyre brand, tyre size and remaining tread depth of the 4 tyres were recorded as follows:-

Chao Yang 215/55R17 (3.8mm)

Chao Yang 215/55R17 (6.1mm)



Chao Yang 215/55R17 (4.3mm)

Chao Yang 215/55R17 (6.2mm)

7. The 4 tyres were observed to be wrapped around standard alloy wheel rims that were found to be without any damage. See photo 1 – 9 below.



Photo 1 shows the mileage of the Electric Taxi at the time of my inspection. The mileage observed was 215,593km.



Photo 2 shows a general view of the Electric Taxi's front body at the time of my inspection. The front portion of the Electric Taxi was observed to have sustained damage. The front bumper was the body part that were damaged as a result of the accident.



Photo 3 shows a general view of the Electric Taxi's right body at the time of my inspection. The right portion of the Electric Taxi was observed to have been unaffected by the accident.



Photo 4 shows a general view of the Electric Taxi's left body at the time of my inspection. The left portion of the Electric Taxi was observed to have been unaffected by the accident.



Photo 5 shows the general view of the Electric Taxi's rear body at the time of my inspection. The Electric Taxi rear was observed to be unaffected by the accident.



Photo 6 shows the condition of the front right tyre of the Electric Taxi, which was observed to be in serviceable condition with remaining tread depth of approximately 6.2mm. The tyre was sufficiently inflated for vehicular operation with no tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread. The 4 tyres of the Electric Taxi were wrapped around standard steel wheel rims without any damage.



Photo 7 shows the condition of the rear right tyre of the Electric Taxi, which was observed to be in serviceable condition with remaining tread depth of approximately 4.3mm. The tyre was also observed to be sufficiently inflated for vehicular operation with no tear, cut or burst mark(s).



Photo 8 shows the condition of the rear left tyre of the Electric Taxi, which was observed to be in serviceable condition with remaining tread depth of approximately 3.8mm. The tyre, which was wrapped around steel wheel rim, was also observed to be sufficiently inflated for vehicular operation. The 4 tyres of the Electric Taxi were wrapped around standard steel wheel rims.



Photo 9 shows the condition of the front left tyre of the Electric Taxi, which was observed to be in serviceable condition with remaining tread depth of approximately 6.1mm. There was also no tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the Electric Taxi's 4 tyres.

Engine Compartment & Operating Fluids

8. Upon examination of the engine compartment of the Electric Taxi, I had observed all the parts and components inside the electric motor compartment to be intact and unaffected by the accident. The brake fluid and coolant were all found to be of sufficient level for operating purposes. Visually, there was also no contamination found to these fluids.
9. Further examination of the engine compartment revealed no sign(s) or indication(s) of fluid leakage and/or fluid stain within the electric motor compartment of the Electric Taxi.
10. My subsequent checks on the underside of the Electric Taxi also revealed no sign(s) or indication(s) of fluid leak and/or fluid stain(s). Visually, the various undercarriage components of the Electric Taxi were all observed to be intact and without any visible damage. See photo 10 – 13 below.



Photo 10 shows a general view of the Electric Taxi's engine compartment. The various parts and components inside the engine compartment were unaffected by the accident. There was also no sign(s) or indication(s) of fluid leakage and/or fluid stain within the engine compartment.



Photo 11 shows the brake fluid reservoir of the Electric Taxi at the time of my inspection. The brake fluid was observed to be of sufficient level (arrowed) and without any visible contamination.




Photo 12 shows checks being carried out to the engine coolant of the Electric Taxi at the time of my inspection. The engine coolant was observed to be of sufficient level (arrowed) and without any visible contamination.



Photo 13 shows the undercarriage of the Electric Taxi, at the area where the electric motor housing are located. I did not find any sign(s) or indication(s) of fluid leak and/or fluid stain(s) on the underside of the Electric Taxi.

Braking System & Steering System

11. Static brake tests conducted on the Electric Taxi revealed no abnormality. The brake booster had responded well to the various tests conducted. There was also no abnormal movement of the brake pedal when it was depressed. In general, the static brake tests had suggested that there was no internal leakage of pressure/vacuum in the braking system of the Electric Taxi. The braking system of the Electric Taxi was likely to be in serviceable condition at the material time. This was taking into consideration that the brake fluid was of sufficient level, and also that there was no sign(s) of brake fluid leakage along the brake hoses and brake pipes.
12. Static test on the steering system of the Electric Taxi also revealed no abnormality to the steering system. I did not experience any abnormal free play and/or other resistance when turning the steering wheel left and right to full lock positions. My visual examination of the various steering components which had included the steering rack and pinion, tie rods, tie rod ends and ball joints revealed that these components were all generally in good condition. See photo 14 - 20 below.



Photo 14 shows the brake hose/pipe (arrowed) at the rear right wheel of the Electric Taxi. No leakage of brake fluid was observed. Visual examination of the various components of the braking system like the drum brake, brake booster, brake pedal etc. had revealed all to be intact and without visible damage.



Photo 15 shows the brake hose/pipe (arrowed) at the rear left wheel of the Electric Taxi. I did not observe any leakage of brake fluid at the time of my inspection of the Electric Taxi. Static tests of the Electric Taxi's braking system had indicated that there was no internal leakage of pressure/vacuum. The undercarriage components of the Electric Taxi were also all found to be intact and without any visible damage.



Photo 16 shows the brake hose/pipe (arrowed) at the front right wheel of the Electric Taxi. I did not observe any leakage of brake fluid at the time of my inspection of the Electric Taxi. Static tests of the Electric Taxi's braking system had indicated that there was no internal leakage of pressure/vacuum. The undercarriage components of the Electric Taxi were also all found to be intact and without any visible damage.




Photo 17 shows the brake hose/pipe (arrowed) at the front left wheel of the Electric Taxi. No leakage of brake fluid was observed. Visual examination of the various components of the braking system like the brake caliper (circled), brake booster, brake pedal etc had revealed all to be intact and without visible damage.



Photo 18 shows the front right wheel of the Electric Taxi turned to its full left. During my steering system test, I did not experience any abnormal free play and/or resistance when I had turned the steering wheel towards the left and right. This would suggest that the steering system of the Electric Taxi was likely to be in serviceable condition at the material time of accident.




Photo 19 shows the various undercarriage components at the front right wheel of the Electric Taxi, in particular the steering tie rod (red arrow) and drive shaft (yellow arrow). The various steering components were all found to be intact, suggesting that the steering system of the Electric Taxi was likely to be in serviceable condition at the material time of accident. There was also no sign of fluid stain observed on the various undercarriage components at the front right wheel of the Electric Taxi.



Photo 20 shows the various undercarriage components at the front left wheel of the Electric Taxi, which had included the steering tie rod (arrowed). The various undercarriage components of the Electric Taxi were all found to be intact without any visible damage.

Electronic Safety / Warning Indicators

13. The Electric Taxi 's automatic self-test of the functionality of its electronic operating systems like the Anti-Lock Brake System (ABS) and Electric Power Steering System (EPS), Supplemental Restraint System (SRS) and Traction Control (TC) during cranking of the engine had indicated that the system were in working condition and without abnormality. This can be established from the warning lights disappearing from the instrument panel after the self-test. See photo 21 & 22 below.



Photo 21 shows the warning light for Anti-Lock Brake System (ABS) and Power Steering System (EPS), Supplemental Restraint System (SRS) and Traction Control (TC) (arrowed) appearing on the instrument panel of the Electric Taxi during the self-test of its various electronic operating systems when its engine was cranked.



Photo 22 shows no warning lights illuminated on the instrument panel of the Electric Taxi after the engine was cranked. This would suggest that there was no abnormality to the electronic operating system of the Electric Taxi, like the ABS, EPS, SRS, and TC etc.

Seat Belts

14. The Front right, front left, rear right and rear left seat belts of the “Electric Taxi” were tested and all the seat belts were able to be fastened securely into the respective pre-tensioners that were fitted at the sides of each seat.

Operational Behaviour of the Electric Taxi

15. A short operational test of the Electric Taxi, to primarily determine whether there was any abnormality to its various operating systems like its engine system, its transmission system, steering system and braking system was subsequently carried out. The test was conducted by driving the Electric Taxi forward, stopping, before reversing and coming to a stop again.
16. During the operational test, the transmission system of the Electric Taxi was able to be shifted to drive mode and reverse mode without any difficulty. There was no abnormal sounds heard and/or abnormal behaviour of the Electric Taxi’s engine system. It was able to move forward and backward normally. The braking system was also found to be in working condition as the Electric Taxi was able to slow down and come to a complete stop upon depressing of the brake pedal. (Refer to photo 2 & 18)

Conclusion

17. From my physical inspection of the Electric Taxi, it appears that its engine system, transmission system, steering system and braking system were all in serviceable condition. I did not find any evidence(s) to suggest that there was possible mechanical failure and/or abnormal behaviour to the Electric Taxi that may have caused and/or contributed to the accident.
18. A short operational test of the Electric Taxi, which I had conducted, did not produce any sign(s) or symptom(s) to suggest that there was any abnormality to its engine system, its transmission system and braking system.

19. The 4 tyres of the Electric Taxi were also found to be in serviceable condition. I did not find any tear, cut or burst mark(s) on the outer and the inner sidewalls as well as across the tread of the 4 tyres. The 4 tyres were also observed to be sufficiently inflated for vehicular operation with remaining tread depth of approximately 3.8mm to 6.2mm.

**Sherwin Beh***Technical Investigator***Ang Bryan Tani***AMSOE, AMIRTE, AFF SAE, M.MATAI, AFF.Inst.AEA**Senior Technical Investigator**Technical Investigation & Reconstructionist (SAE-A)*

DISCLAIMER OF LIABILITY TO THIRD PARTIES: - This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part does so at his or her own risk.