

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS4/AIS22010890/NVY3E2**Date:** 05/12/2022**REFERENCE**

Insured/Claimant:	LEE SAI SING	Policy No:	SP2002269793		
Date of Loss:	30/10/2022	Nature of Claim:	OD	Claim No:	202222007815-FIRE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>EP8338E</b>		Engine No:	65692980062339
Make & Model:	MERCEDES-BENZ GLS400, 3.0 4MATIC AUTO (A)		Chassis No:	WDC1679232A074155
Reg. Date:	14/07/2020 (Man. Year: 2019)		Odometer:	0 km
Colour:	Grey			
Engine Capacity:	2925 cc			
Market Value/New Car Price:	S\$350,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	285/45 R22	Rear Tyre Size:	325/40 R22
Front Left Side:	Continental 2 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	01/11/2022	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	02/11/2022	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	0.0 days		

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$350,000.00
OMV :	\$85,620.00
PARF Rebate (1) :	\$94,587.00
Quota Premium Paid :	\$35,889.00
COE Rebate (2) :	\$27,630.00
Total Rebate (1) + (2) = :	\$122,217.00

The total amount incurred will be Market Value \$350,000.00 minus Total Rebate \$122,217.00 = \$227,783.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 05 Dec 2022)

**Parts:**            143                    MERCEDES-BENZ GLS400 3.0 4MATIC AUTO (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's            (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for EP8338E)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**