


11/11/22, 4:51 PM

https://vacsweb.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
4	Main	TO RESPRAY VIEW MIRROR	180.00	70	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
6	Main	TO RESRAY REAR DOOR LH	378.00	200	
7	Main	TO RESPRAY REAR FENDER LH	378.00	200	
8	Main	TO RESPRAY REAR BUMPER	378.00	0 <i>xan</i>	
Total:			2,628.00	1,170.00 ✓	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 <i>xan</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 <i>xan</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0 <i>xan</i>	
4	Main	TO TRANSFER DOOR MECHANISM	240.00	0 <i>xan</i>	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>xan</i>	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 <i>xan</i>	
Total:			840.00	0.00	

**Summary**

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,243.53	83.45
Total Labour Cost	1,014.00	600.00
Total Spray Painting	2,628.00	1,170.00
Other	840.00	0.00
Overall Total	9,725.53	1,853.45
Lump Sum Repair Option		☒
Lump Sum Total	9,750.00	1,850.00
Surveyor Approved Amount		1,850.00

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			HINGE ASSY, FRONT DOOR , LOWER LH	1	120.00	120.00	25.00	90.00	Replace	0	0	Not Give	Xm
Standard	Main			CHECK ASSY, FRONT DOOR	1	199.40	199.40	25.00	149.55	Replace	0	0	Not Give	Xm
Standard	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,454.40	1,454.40	10.00	1,308.96	Replace	1	0.00	Replace	Xm
Standard	Main			COVER, OUTER MIRROR, LH	1	117.80	117.80	25.00	88.35	Replace	1	0	Repair	R
Standard	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,401.70	1,401.70	25.00	1,051.28	Replace	1	0	Repair	R
Standard	Main			HINGE ASSY, REAR DOOR , UPPER LH	1	107.00	107.00	25.00	80.25	Replace	0	0	Not Give	Xm
Standard	Main			HINGE ASSY, REAR DOOR , LOWER LH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	Xm
Standard	Main			CHECK ASSY, REAR DOOR	1	199.40	199.40	25.00	149.55	Replace	0	0	Not Give	Xm
Standard	Main			PANEL SUB-ASSY, FENDER REAR LH	1	943.10	943.10	25.00	707.33	Replace	1	0	Repair	R
Total Spare Part Cost									7,261.74	Surveyor Total		104.33		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									5,243.53	Final Sur Total		83.46		

Labour's Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,014.00	600	
Total:			1,014.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	

11/11/22, 4:51 PM

https://www.lkkautoconsultants.com

	Estimator Assessment(\$)	Surveyor Assessment(\$)
No of Repair Days*	7	6
Remarks	-	LUMP SUM REPAIR / RESURVEY AFTER REPAIR
Surveyor Name		Rasul
Signature		
Survey Date	01/11/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: