

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22010923/KVY3E2**Date:** 20/06/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962166
Claimant Vehicle No :	SMH678Z	Insured Vehicle No :	SLV3948M
Date of Loss:	28/10/2022	Nature of Claim:	TP
		Claim No:	289020

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH678Z	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ E200 AVG, 2.0 (R18 LED) (A)	Chassis No:	WDD2130422A078932
Reg. Date:	01/11/2016 (Man. Year: 2016)	Odometer:	78097 km
Colour:	Metallic Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,064.10	6,548.10	516.00	7.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,010.00	550.00	35.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,624.10	7,558.10	1,066.00	12.36
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	8,624.10	6,000.00	2,624.10	30.43
+ GST 8.00/8.00% (S\$)	689.93	480.00	209.93	30.43
Nett Amount (S\$)	9,314.03	6,480.00	2,834.03	30.43

INSPECTION

Date of Assignment:	02/11/2022	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047
Date Inspected:	21/12/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	143	MERCEDES-BENZ E200 AVG 2.0 (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH678Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,975.00 FL	*1,975.00 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	24.00 FL	*24.00 FL
3	1		*HEADLAMP RH	Cut	3,870.00 FL	*3,870.00 FL
4	1		*FRONT RH FENDER	Bent	1,180.00 FL	*1,180.00 FL
5	6		*FRONT RH FENDER INNER SHIELD CLIP	Necessary	60.00 FL	*60.00 FL
6	1		*FRONT RH RIM 18 (LOCAL REPAIR)	Scratched	740.00 FN	*150.00 F

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	7,849.00	7,259.00
- List Item Discount on L Items 10.00/10.00% (S\$)	710.90	710.90
- Nett Item Discount on N Items 10.00/0.00% (S\$)	74.00	0.00
Total Parts (S\$)	7,064.10	6,548.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, HEADLAMP, FRT RH FENDER; KNOCKING & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME	New	700.00	450.00
2	PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, FRT RH FENDER & INNER PANEL & ALL AFFECTED AREAS	New	700.00	450.00
3	REMOVE & REFIX FRT RH RIM, TYRE, BALANCE & REALIGN THE SAME	New	50.00	20.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	80.00	60.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,560.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >