

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22010924/TWY3Q2**Date:** 28/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU011956	
Claimant Vehicle No :	SHA7834P	Insured Vehicle No :	SDL12E	
Date of Loss:	21/10/2022	Nature of Claim:	TP	Claim No: M2205911

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7834P	Engine No:	D4DFDU553645
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMFU069431
Reg. Date:	30/05/2015 (Man. Year: 2015)	Odometer:	648663 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,600.16	1,489.76	1,110.40	42.71
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,480.00	880.00	600.00	40.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,091.16	2,380.76	1,710.40	41.81
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,091.16	1,900.00	2,191.16	53.56
+ GST 7.00/7.00% (S\$)	286.38	133.00	153.38	53.56
Nett Amount (S\$)	4,377.54	2,033.00	2,344.54	53.56

INSPECTION

Date of Assignment:	01/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7834P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,052.20 FL	*1,052.20 FL
2	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRONT FENDER LH	Bent	663.00 FL	*663.00 FL
4	1		*HEADLAMP LH	Not Necessary	1,388.00 FL	*- FL
5	1		*FRONT FENDER ADVERTISEMENT STICKER LH	Cut	100.00 F	*100.00 F
					Sub Total (S\$)	3,225.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	625.04
					Total Parts (S\$)	2,600.16

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK LIGHTINGS	New	40.00	0.00
4	TUFF KOTE	New	40.00	30.00
Gross Labour Cost (\$\$)			1,480.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >