

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22010939/AYA3Q2**Date:** 01/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210141726
<b>Claimant Vehicle No :</b>	GBH7778C	<b>Insured Vehicle No :</b>	SNC8513C
Date of Loss:	30/09/2022	Nature of Claim:	TP
		Claim No:	6497535711SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH7778C</b>		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M)	Engine No:	4P10C21632
Reg. Date:	24/11/2017 (Man. Year: 2017)	Chassis No:	FEA01BA20671
Colour:	Blue	Odometer:	96439 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Transporter 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	Transporter 6 mm	Rear Right Side:	KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,340.80	1,996.50	3,344.30	62.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	880.00	2,100.00	70.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,320.80</b>	<b>2,876.50</b>	<b>5,444.30</b>	<b>65.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,320.80</b>	<b>2,300.00</b>	<b>6,020.80</b>	<b>72.36</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		38.45		
<b>Nett Liability (S\$)</b>		<b>2,638.45</b>		

**INSPECTION**

Date of Assignment:	31/10/2022	
Date Inspected:	31/10/2022 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FUEL TANK	Dented	1,890.00 FL	*1,890.00 FL
2	2		*FUEL TANK BELT HOLDER	Bent	572.00 FL	*572.00 FL
3	2		*FUEL TANK BRACKET	Not Necessary	1,090.00 FL	*- FL
4	1		*FUEL TANK CAP	Not Necessary	160.00 FL	*- FL
5	1		*SLIDING DOOR RAILWAY RH	Repair	1,200.00 FS	*- FS
6	1		*REAR BOX CORNER PILLAR COVER (ALUMINUM)	Repair	550.00 FS	*- FS
7	1		*DIESEL	Necessary	250.00 FS	*150.00 FS
					<b>Sub Total (\$\$)</b>	<b>5,712.00      2,612.00</b>
					<b>- List Item Discount on L Items 10.00/25.00% (\$\$)</b>	<b>371.20      615.50</b>
					<b>Total Parts (\$\$)</b>	<b>5,340.80      1,996.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT ,KNOCK ,WELD ,CUT ,ADJUST STRAIGHTEN GRAZE ALIGN	New	1,600.00	400.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,200.00	400.00
3	REMOVE AND REFIX FUEL TANK	New	180.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>2,980.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >