

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010944/ANP3E2**Date:** 19/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00029202201

**Claimant Vehicle
No :** SJF2292K**Insured Vehicle
No :** SMW5357M

Date of Loss: 16/10/2022

Nature of Claim: TP

Claim
No: SNM22D207632/C02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJF2292K**

Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A)

Engine No: 1NZC988670

Reg. Date: 23/05/2008 (Man. Year: 2008)

Chassis No: NZE1416075390

Colour: Silver

Odometer: 201090 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,050.00	1,678.75	6,371.25	79.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,290.00	1,440.00	52.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,780.00	2,968.75	7,811.25	72.46
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	10,780.00	2,300.00	8,480.00	78.66

INSPECTION

Date of Assignment: 31/10/2022

Date Inspected: 04/11/2022 Inspected At:

25 Kaki Bukit Road 4 #05-76, Synergy@KB
Repairer: Jd Motorsports Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2023)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF2292K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,680.00 FL	*1,165.00 FL
2	2		*REAR RH DOOR HINGES	Not Necessary	250.00 FL	*- FL
3	1		*REAR RH DOOR INNER LOCK	Not Necessary	680.00 FL	*- FL
4	1		*REAR RH DOOR LOCK CATCH	Not Necessary	85.00 FL	*- FL
5	1		*REAR RH DOOR CHECKER	Not Necessary	125.00 FL	*- FL
6	1		*REAR RH DOOR WEATHERSTRIP	Not Necessary	280.00 FL	*- FL
7	1		*REAR RH DOOR POWER WINDOW MOTOR	Not Necessary	560.00 FL	*- FL
8	1		*REAR RH DOOR POWER WINDOW REGULATOR	Not Necessary	390.00 FL	*- FL
9	1		*REAR RH DOOR OUTER CHROME MOULDING	Not Necessary	250.00 FL	*- FL
10	1		*REAR BUMPER	Deformed	650.00 FL	*495.00 FL
11	1		*REAR BUMPER SIDE RETAINER RH	Damaged	120.00 FL	*45.00 FL
12	1		*REAR RH ROCKER PANEL	Not Necessary	1,750.00 FL	*- FL
13	1		*TYRES RIM	Cut	600.00 FN	*400.00 F
14	1		*REAR RH FENDER	Repair	2,350.00 FL	*- FL
15	1		*REAR RH FENDER INNERSHIELD	Not Necessary	360.00 FL	*- FL
16	1		*REAR RH FENDER INNERSHIELD CLIP	Not Necessary	65.00 FL	*- FL
17	1		*REAR WINDSCREEN MOULDING	Not Necessary	285.00 FL	*- FL
18	2		*WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
19	1		*TYRES	Not Necessary	130.00 FS	*- FS
20	1		*TYRES BALANCING	Not Necessary	10.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	10,670.00	2,105.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,470.00	426.25
- Nett Item Discount on N Items 25.00/0.00% (\$)	150.00	0.00
Total Parts (\$)	8,050.00	1,678.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY LABOUR & PARTS TO REPLACE ABOVE MENTIONED PARTS	New	1,500.00	600.00
2	TO SUPPLY LABOUR & PAINT TO SPRAY ACCIDENT AFFECTED AREA	New	750.00	600.00
3	TO SUPPLY LABOUR & SPARY ANTI-RUST ACCIDENT AFFECTED AREA	New	180.00	60.00
4	TO SUPPLY LABOUR TO RE-WIRE ELECTRICAL PARTS	New	150.00	30.00
5	TO SUPPLY LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	0.00
Gross Labour Cost (\$\$)			2,730.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >