



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 7274K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD FAIRING	BROKEN	65.00	65.00
1	HEAD INNER PANEL	BROKEN	45.00	45.00
1	HANDLE BAR	BENT	75.00	75.00
1	TRIPLE CRAMP	BENT	280.00	280.00
1	MUDGUARD	BROKEN	55.00	55.00
1	SET FORK	BENT	280.00	280.00
1	(LH) SIDE FAIRING NO.2	BROKEN	80.00	80.00
1	(LH) SIDE FAIRING NO.3	BROKEN	75.00	75.00
1	(RH) SIDE FAIRING NO.4	BROKEN	75.00	75.00
1	(RH) SIDE FAIRING NO.5	BROKEN	80.00	80.00
1	FRONT FAIRING	BROKEN	65.00	65.00
1	BRAKE DISC	BENT	95.00	95.00
1	RIM	BROKEN	280.00	280.00
1	FRONT WHEEL SHAFT	BENT	25.00	25.00
	LESS 10% DISCOUNT		-	-157.50
			1,575.00	1,417.50
	<u>LABOUR</u>			
	BODY ALIGNMENT.		450.00	300.00
	LABOUR.		180.00	150.00
			630.00	450.00
	GRAND TOTAL		2,205.00	1,867.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00

Report Ref No. CS/LAW22010946/Ewy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.