

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS4/FWD22010948/UQY3M4**Date:** 25/11/2022**REFERENCE**

Insured/Claimant: ABDUL HAFFIZ BIN ABDUL ALEEM Policy No: PNMC2022-00004679
Date of Loss: 21/10/2022 Nature of Claim: OD Claim No: 1202200044463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBB7707P**
Make & Model: YAMAHA YZF-R6S, 599cc Engine No: J511E028285
Reg. Date: 18/07/2007 (Man. Year: 2007) Chassis No: JYARJ111000023628
Colour: White Odometer: 0 km
Engine Capacity: 599 cc
Market Value/New Car Price: S\$10,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 ZR17 Rear Tyre Size: 180/55 ZR17
Front Left Side: Michelin 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,168.95	8,026.25	3,142.70	28.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	500.00	220.00	30.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,888.95	8,526.25	3,362.70	28.28
+ GST 7.00/7.00% (S\$)	832.23	596.84	235.39	28.28
Nett Amount (S\$)	12,721.18	9,123.09	3,598.09	28.28

INSPECTION

Date of Assignment: 02/11/2022 Present Location: Ban Hock Hin Co. Pte Ltd (HQ)
Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected: 03/11/2022 Inspected At: No. 6 Defu Lane 4
Singapore 539410
Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$2,544.60 NETT)

TOTAL LOSS ASPECT

Market Value :	\$10,000.00
OMV :	\$ 9,184.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$ 6,256.00
COE Rebate (2) :	\$ 2,758.00
Total Rebate (1) + (2) = :	\$ 2,758.00

The total amount incurred will be Market Value \$10,000.00 minus Total Rebate \$2,758.00 = \$7,242.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 25 Nov 2022)	
Parts:	N/A	YAMAHA YZF-R6S 599cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB7707P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bttery	Not Necessary	140.00 F	*- F
2	2		*Bearing Steering Cone Lower	Burnt	96.00 F	*96.00 F
3	1		*Bolt Damper	Burnt	2.00 F	*2.00 F
4	1		*Bracket 5	Burnt	15.00 F	*15.00 F
5	1		*Bracket 7	Burnt	30.00 F	*30.00 F
6	1		*Bracket Side Stand	Burnt	50.00 F	*50.00 F
7	1		*Cable Clutch	Burnt	50.00 F	*50.00 F
8	1		*Cable Throttle	Burnt	29.00 F	*29.00 F
9	1		*Caliper Brake Front Assy LH	Burnt	625.00 F	*625.00 F
10	1		*Cap Coolant	Burnt	7.00 F	*7.00 F
11	1		*Cap Radiator	Burnt	22.80 F	*22.80 F
12	1		*Chain	Burnt	160.00 F	*160.00 F
13	1		*Clamp 1	Burnt	8.00 F	*8.00 F
14	1		*Clip	Necessary	3.00 F	*3.00 F
15	2		*Clip Fork Front	Burnt	4.00 F	*4.00 F
16	4		*Clip Hose	Burnt	8.00 F	*8.00 F
17	1		*Coil Ignition	Burnt	100.00 F	*100.00 F
18	1		*Coolant	Necessary	25.00 F	*25.00 F
19	1		*Cord Starter Motor	Burnt	69.00 F	*69.00 F
20	1		*Cover 1	Burnt	11.00 F	*11.00 F
21	1		*Cover Crankcase Magnet	Burnt	79.00 F	*79.00 F
22	1		*Cover Radiator	Burnt	6.00 F	*6.00 F
23	1		*Cover Sprocket Front	Burnt	16.00 F	*16.00 F
24	1		*Cover Strainer Assy	Burnt	142.00 F	*142.00 F
25	1		*Coverset Assy	Burnt	1,060.60 F	*1,060.60 F
26	1		*Damper 2	Burnt	2.00 F	*2.00 F
27	1		*Damper Air Shroud	Burnt	2.00 F	*2.00 F
28	1		*Damper Air Shroud 3	Burnt	2.00 F	*2.00 F
29	2		*Damper Locating	Burnt	8.00 F	*8.00 F
30	1		*Dust Cover Shift Shaft	Burnt	3.00 F	*3.00 F
31	1		*Fan Radiator	Burnt	262.00 F	*262.00 F
32	1		*Filter Oil	Burnt	28.00 F	*28.00 F
33	1		*Fork Tube Inner LH	Not Necessary	340.90 F	*- F
34	1		*Fuel Pipe 1	Burnt	37.00 F	*37.00 F
35	1		*Gasket Crankcase Cover 1	Burnt	15.00 F	*15.00 F
36	4		*Gasket Exhaust Pipe	Necessary	32.00 F	*32.00 F
37	1		*Gasket Oil Pump Cover 1	Necessary	15.00 F	*15.00 F
38	1		*Gasket Strainer Cover	Necessary	13.00 F	*13.00 F
39	1		*Guide Side Stand	Burnt	24.00 F	*24.00 F
40	1		*Horn	Burnt	37.00 F	*37.00 F
41	1		*Hose	Burnt	11.00 F	*11.00 F
42	1		*Hose	Burnt	4.00 F	*4.00 F
43	1		*Hose	Burnt	37.00 F	*37.00 F
44	1		*Hose 1	Burnt	14.00 F	*14.00 F
45	1		*Hose 2	Burnt	11.00 F	*11.00 F
46	1		*Hose 3	Burnt	4.00 F	*4.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*Hose 4	Burnt	21.00 F	*21.00 F
48	1		*Hose 5	Burnt	5.00 F	*5.00 F
49	1		*Hose 7	Burnt	12.00 F	*12.00 F
50	1		*Hose 8	Burnt	19.00 F	*19.00 F
51	2		*Hose Bend 1	Burnt	16.00 F	*16.00 F
52	1		*Hose Brake (HEL)	Burnt	190.90 F	*190.90 F
53	2		*Hose Clamp Assy (Bottom Hose)	Burnt	10.00 F	*10.00 F
54	2		*Hose Elbow Radiator	Burnt	7.40 F	*7.40 F
55	1		*Joint Hose 2	Burnt	30.00 F	*30.00 F
56	1		*Joint Shift Shaft	Burnt	20.00 F	*20.00 F
57	2		*Joint, Carbruretor 1	* Check	64.00 F	*- F
58	2		*Joint, Carbruretor 2	* Check	64.00 F	*- F
59	1		*Mid Seal Oil (12x22x5) Pedal Grear	Burnt	5.00 F	*5.00 F
60	1		*Motor Starter Assy	Burnt	319.00 F	*319.00 F
61	1		*Oil Brake Dot 4	* Check	14.60 F	*- F
62	4		*Oil Engine (50%)	Necessary	51.60 F	*25.80 F
63	1		*Oil Fork	Not Necessary	7.50 F	*- F
64	2		*O-Ring	Not Necessary	3.40 F	*- F
65	1		*Pedal Gear Assy	Burnt	91.00 F	*91.00 F
66	1		*Pipe 1	Burnt	11.00 F	*11.00 F
67	1		*Pipe Exhaust Assy	Burnt	2,046.00 F	*2,046.00 F
68	1		*Pipe Hose Radiator	Burnt	28.00 F	*28.00 F
69	1		*Plate Radiator	Burnt	8.00 F	*8.00 F
70	1		*Protector Heat	Burnt	57.00 F	*57.00 F
71	1		*Radiator Assy	Burnt	387.00 F	*387.00 F
72	1		*Rectifier & Regulator Assy	Burnt	104.00 F	*104.00 F
73	1		*Relay Replacement	Burnt	28.00 F	*28.00 F
74	1		*Rod Shift 1	Burnt	34.00 F	*34.00 F
75	2		*Seal Dust Fork	Not Necessary	22.00 F	*- F
76	2		*Seal Oil Fork	Not Necessary	40.00 F	*- F
77	1		*Shift Arm	Burnt	57.00 F	*57.00 F
78	1		*Spring Tension	Burnt	6.00 F	*6.00 F
79	1		*Sprocket Front	Burnt	74.00 F	*74.00 F
80	1		*Sprocket Rear Std	Burnt	85.00 F	*85.00 F
81	1		*Stand Side	Burnt	177.00 F	*177.00 F
82	1		*Stator Assy	* Check	308.00 F	*- F
83	1		*Switch Side Stand	Burnt	66.00 F	*66.00 F
84	1		*Tank Coolant Recovery	Burnt	24.00 F	*24.00 F
85	1		*Thermosensor Assy	Burnt	56.60 F	*56.60 F
86	1		*Throttle Body Assy	* Check	1,989.00 F	*- F
87	1		*Valve Solenoid	* Check	105.00 F	*- F
88	1		*Wire Harness Assy	Burnt	819.00 F	*819.00 F
89	5		*Petrol	Not Necessary	18.50 F	*- F
90	11		*Tube	Burnt	7.15 F	*7.15 F

F=Franchise part.

Total Parts (S\$)	11,168.95	8,026.25
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Labour	New	720.00	500.00
Gross Labour Cost (\$\$)			720.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >