

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010952/ANP3Q2**Date:** 05/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00154432100
Claimant Vehicle No :	SNC7941G	Insured Vehicle No :	GBC4437H
Date of Loss:	26/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207768/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC7941G	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2040452A639126
Reg. Date:	01/01/2012 (Man. Year: 2012)	Odometer:	165241 km
Colour:	Red		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Altenzo 6 mm	Rear Left Side:	Altenzo 6 mm
Front Right Side:	Altenzo 6 mm	Rear Right Side:	Altenzo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,550.50	6,360.30	11,190.20	63.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	850.00	2,960.00	77.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,360.50	7,210.30	14,150.20	66.24
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	21,360.50	5,700.00	15,660.50	73.32

INSPECTION

Date of Assignment:	01/11/2022	
Date Inspected:	01/11/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC7941G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	274.00 FL	*- FL
2	6		*FRONT BUMPER SIDE BRACKET	Not Necessary	268.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	799.00 FL	*- FL
4	1		*FRONT FENDER RH	Not Necessary	857.00 FL	*- FL
5	2		*FRONT FENDER INNER COWLING	Not Necessary	318.00 FL	*- FL
6	2		*FRONT HEADLAMP	Cracked	2,144.00 FL	*2,144.00 FL
7	2		*FRONT HEADLAMP PANEL	Not Necessary	468.00 FL	*- FL
8	1		*BONNET	Dented	1,647.00 FL	*1,647.00 FL
9	1		*BONNET LOGO	Necessary	86.00 FL	*86.00 FL
10	2		*BONNET HINGE	Not Necessary	174.00 FL	*- FL
11	2		*BONNET DAMPER	Not Necessary	218.00 FL	*- FL
12	2		*BONNET BOTTOM LOCK	Not Necessary	296.00 FL	*- FL
13	1		*BONNET INSULATOR	Not Necessary	298.00 FL	*- FL
14	2		*BONNET STOPPER	Not Necessary	38.00 FL	*- FL
15	1		*BONNET INNER RUBBER	Not Necessary	98.00 FL	*- FL
16	1		*FRONT RADIATOR TOP PANEL	Not Necessary	1,217.00 FL	*- FL
17	1		*FRONT RADIATOR TOP PANEL GARNISH	Cracked	190.00 FL	*190.00 FL
18	2		*FRONT RADIATOR SUPPORT STAND PANEL	Not Necessary	356.00 FL	*- FL
19	1		*OUTSIDE TEMPERATURE SENSOR	Not Necessary	147.00 FL	*- FL
20	1		*FRONT TURBO COOLER	Not Necessary	1,726.00 FL	*- FL
21	1		*COOLER AIR GUARD	Not Necessary	172.00 FL	*- FL
22	2		*AIRCON CONDENSER SIDE AIR GUARD	Not Necessary	172.00 FL	*- FL
23	1		*AIRCON CONDENSER	Not Necessary	1,282.00 FL	*- FL
24	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*SET FRONT BUMPER (SPECIAL TYPE)	Deformed	2,800.00 FS	*1,400.00 FS
27	1		*FRONT BUMPER CENTER GRILLE LOGO (SPECIAL TYPE)	Cracked	800.00 FS	*250.00 FS
28	1		*FRONT CENTER GRILLE C/W CHROME (SPECIAL TYPE)	Smashed	1,600.00 FS	*1,000.00 FS
29	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
30	1		*SET FRONT RADIATOR TOP PANEL GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
31	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
32	1		*RADIATOR COOLANT	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,875.00	6,767.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,324.50	406.70
Total Parts (\$\$)	17,550.50	6,360.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	400.00
3	REFOCUS HEADLAMP BEAM	New	80.00	50.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
6	REMOVE AND REFIX TURBO COOLER	New	80.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	0.00
Gross Labour Cost (\$\$)			3,810.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >