

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010954/TVP3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00010102200

Claimant Vehicle No : SMS1009R **Insured Vehicle No :** PC5836S

Date of Loss: 31/10/2022 Nature of Claim: TP Claim No: SNM22D207838/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS1009R**

Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ185309

Reg. Date: 11/02/2020 (Man. Year: 2019) Chassis No: JTEZB3GH10J005454

Colour: Black Odometer: 30785 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,141.10	5,487.10	6,654.00	54.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,209.17	4,459.17	2,750.00	38.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,350.27	9,946.27	9,404.00	48.60
+ GST 7.00/7.00% (S\$)	1,354.52	696.24	658.28	48.60
Nett Amount (S\$)	20,704.79	10,642.51	10,062.28	48.60

INSPECTION

Date of Assignment: 01/11/2022

Date Inspected: 18/11/2022 Inspected At: Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS1009R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*PANEL SUB-ASSY ,RR	Bent	1,680.90 FS	*1,680.90 FS
3	1		*STRIPE RR DOOR	Necessary	47.40 FS	*47.40 FS
4	1		*STRIPE RR DOOR	Necessary	26.40 FS	*26.40 FS
5	1		*TAPE,BLACK OUT RR	Necessary	26.40 FS	*26.40 FS
6	1		*TAPE,BLACK OUT RR	Necessary	31.80 FS	*31.80 FS
7	1		*TAPE,BLACK OUT RR	Necessary	18.50 FS	*18.50 FS
8	1		*WEATHERSTRIP ,RR	Not Necessary	181.60 FS	*- FS
9	1		*PANEL SUB-ASSY	Repair	1,531.10 FS	*- FS
10	1		*MOULDING RR DOOR	Cut	142.50 FS	*142.50 FS
11	1		*MOULDING ASSY BODY	Cut	734.20 FS	*734.20 FS
12	1		*COVER ,RR BUMPER	Repair	904.00 FS	*- FS
13	1		*COVER ,RR BUMPER	Not Necessary	466.00 FS	*- FS
14	10		*PIECE ,RR BUMPER	Necessary	45.00 FS	*45.00 FS
15	1		*WHEEL ,DISC	Cut	2,700.60 FS	*2,700.60 FS
16	1		*ABSORBER ,SHOCK ,RR	Not Necessary	178.60 FS	*- FS
17	1		*ARM ASSY ,RR	Not Necessary	315.70 FS	*- FS
18	1		*ARM ASSY ,TRAILING	Not Necessary	574.10 FS	*- FS
19	1		*CARRIER ,SUB-ASSY RR	Not Necessary	503.40 FS	*- FS
20	1		*ARM ASSY ,RR	Not Necessary	524.40 FS	*- FS
21	1		*ARM ASSY ,UPR	Not Necessary	381.30 FS	*- FS
22	1		*HUD & BRG ASSY ,RR	Not Necessary	1,090.40 FS	*- FS
23	4		*RIVET	Necessary (2 PCS ONLY)	6.80 FS	*3.40 FS
Total Parts (S\$)						12,141.10
						5,487.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	New	274.77	274.77
2	CHECK LIGHTING & WIRING SYSTEM	New	122.40	122.40
3	TRANSFER & INSTALL COMPONENTS TO NEW DOOR	New	360.00	360.00
4	SUPPLY SEALANT -RH REAR DOOR	New	60.00	60.00
5	REMOVE & INSTALL GARNISH ,CARPET AND TRIMMING ASSY TO ASSIST REPAIR	New	360.00	0.00
6	REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING	New	72.00	72.00
7	REPLACE RH REAR SUSPENSION SYSTEM	New	360.00	0.00
8	CONDUCT FULL WHEEL ALIGNMENT	New	180.00	180.00
9	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
10	REPLACE RH REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH REAR ACCIDENT AFFECTED AREAS	New	2,880.00	1,440.00
11	RESPRAY JOB ON RH REAR ACCIDENT AFFECTED AREAS	New	2,360.00	1,770.00
Gross Labour Cost (S\$)			7,209.17	4,459.17

Report was unsubmitted during this print-out.

< END OF ESTIMATES >