

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22010957/KVP3Q2  
**Date:** 22/11/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00019352200
Claimant Vehicle No :	SJN6208L	Insured Vehicle No :	SNG8340M
Date of Loss:	31/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207823/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN6208L	Engine No:	1NZD289617
Make & Model:	TOYOTA PREMIO, 1.5 F (A)	Chassis No:	NZT2603037801
Reg. Date:	23/02/2009 (Man. Year: 2008)	Odometer:	152779 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	KAPSEN 8 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	KAPSEN 8 mm	Rear Right Side:	Michelin 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,600.50	3,830.92	6,769.58	63.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,430.00	1,420.00	49.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,450.50</b>	<b>5,260.92</b>	<b>8,189.58</b>	<b>60.89</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,100.00</b>		
	13,450.50	4,100.00	9,350.50	69.52
<b>+ GST 7.00/7.00% (\$\$)</b>	941.54	287.00	654.54	69.52
<b>Nett Amount (\$\$)</b>	<b>14,392.04</b>	<b>4,387.00</b>	<b>10,005.04</b>	<b>69.52</b>

### INSPECTION

Date of Assignment:	01/11/2022	
Date Inspected:	01/11/2022	Inspected At:
Estimated Period of Repair:	5.0 days	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
<b>Parts:</b>	143	TOYOTA PREMIO 1.5 F (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJN6208L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,513.00 FL	*881.70 FL
2	1		*BOOTLID INNER TRIM	Serviceable	181.00 FL	*- FL
3	2		*BOOTLID HINGE	Repair	134.00 FL	*- FL
4	1		*BOOTLID LOCK	Dented	359.00 FL	*359.00 FL
5	1		*BOOTLID LOCK STRIKER	Repair	65.00 FL	*- FL
6	1		*BOOTLID RELEASE SWITCH	Serviceable	324.00 FL	*- FL
7	1		*BOOTLID RELEASE CABLE	Serviceable	153.00 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP (50%)	Deformed / Dented	138.75 FS	*92.50 FS
9	2		*LICENCE PLATE LAMP	Serviceable	184.00 FL	*- FL
10	1		*BOOTLID CHROME GARNISH	Serviceable	277.00 FL	*- FL
11	2		*BOOTLID HINGE GARNISH	Serviceable	98.00 FL	*- FL
12	1		*BOOTLID TOYOTA LOGO	Necessary	61.00 FL	*61.00 FL
13	1		*BOOTLID PREMIO EMBLEM	Necessary	47.00 FL	*47.00 FL
14	1		*BOOTLID F EMBLEM	Necessary	42.00 FL	*42.00 FL
15	2		*BOOTLID LAMP	Serviceable	1,148.00 FL	*- FL
16	2		*BOOTLID LAMP SPONGE SEAL	Serviceable	16.00 FL	*- FL
17	1		*REAR BUMPER	Bent	1,188.00 FL	*1,188.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Distorted	114.00 FL	*114.00 FL
19	1		*REAR BUMPER REINFORCEMENT	No such part	576.00 FL	*- FL
20	1		*REAR BUMPER LOWER COWLING	Serviceable	188.00 FL	*- FL
21	2		*TAILLAMP	Mtg Cracked	1,578.00 FL	*977.20 FL
22	2		*TAILLAMP SPONGE SEAL	Necessary	16.00 FL	*16.00 FL
23	2		*TAILLAMP PANEL	Repair	294.00 FL	*- FL
24	2		*TAILLAMP LOWER BRACKET	Serviceable	66.00 FL	*- FL
25	1		*END PANEL	Bent	732.00 FL	*732.00 FL
26	1		*END PANEL TOP GARNISH	Dented	164.00 FL	*164.00 FL
27	1		*SPARE TYRE FLOOR PANEL	Repair	895.00 FL	*- FL
28	1		*SPARE TYRE TOP BOARD	Serviceable	227.00 FL	*- FL
29	1		*REAR BUMPER IMPACT ABSORBER	Serviceable	239.00 FL	*- FL
30	2		*REAR BUMPER SPLASH GUARD	Serviceable	174.00 FL	*- FL
31	1		*REAR LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS
32	1		*REVERSE CAMERA	Serviceable	550.00 FS	*- FS
33	1		*REVERSE SENSOR	Dented	380.00 FS	*200.00 FS
34	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	45.00 FS	*- FS
35	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
36	1		*REAR BUMPER DIFFUSER	No such part	800.00 FS	*- FS
37	1		*SPARE TYRE FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
38	1		*END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
39	6		*END PANEL TOP GARNISH CLIPS	Necessary	27.00 FS	*27.00 FS
40	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)**      **13,363.75**      **4,976.40**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,763.25	1,145.48
Total Parts (S\$)					10,600.50	3,830.92

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	600.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE ,REFIT BOOTLID COMPONENTS AND REPLACE BOOTLID,CHECK AND RE-ADJUST CLOSE GAP ,ALIGNMENT AND WATER SEEPAGE	New	100.00	50.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,200.00	700.00
5	TO UNDERCOAT ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,850.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >