

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 3024A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	OS REAR LAMP COVER (CONSISTENT)	CRACKED	800.00	800.00
1	OS REAR BUMPER (CONSISTENT)	CRACKED	560.00	560.00
1	REAR BUMPER FIXATION-ANGLE (CONSISTENT)	BENT	86.00	86.00
1	REAR BUMPER FIXATION-ANGLE (CONSISTENT)	BENT	86.00	86.00
1	REAR BUMPER FIXATION-ANGLE (CONSISTENT)	BENT	86.00	86.00
1	REAR REFLECTOR CORO -RED (CONSISTENT)	MISSING	196.00	196.00
1	EXHAUST FLAP ASSY (CONSISTENT)	BENT	2,908.00	2,908.00
2	HINGE ASSY (EXHAUST FLAP) (CONSISTENT)	BENT	512.00	512.00
1	DOVETAIL FEMALE HAPPICH (CONSISTENT)	NOT NECESSARY	30.00	-
1	DOVETAIL MALE HAPPICH (CONSISTENT)	NOT NECESSARY	30.00	-
1	EXTERIOR SIDE PANELLING PANEL (CONSISTENT)	BENT	240.00	240.00
1	EXTERIOR SIDE PANELLING PANEL (CONSISTENT)	BENT	280.00	280.00
1	EXHAUST COMPARTMENT SUPPORT TUBE (CONSISTENT)	BENT	160.00	160.00
			5,974.00	5,914.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE : -ITEM NOS 1-3. }		3,900.00	2,275.00
	TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS: -OS REAR PILLAR SUPPORT.}		1,300.00	-
	SPRAY PAINTING: -OS REAR LAMP COVER -OS REAR BUMPER -EXHAUST FLAP -OS REAR SIDE PANEL -OS SMALL BODY BOTTOM PANEL.		3,200.00	1,280.00
			8,400.00	3,555.00
	GRAND TOTAL		14,374.00	9,469.00



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 9,469.00

Report Ref No. CC4/ASM22010960/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

/mont

HO LEONG CHUAN

Automotive Assessor