

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22010962/UNP3Q2**Date:** 14/11/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00134742200
<b>Claimant Vehicle No :</b>	GBF8492E	<b>Insured Vehicle No :</b>	SFY8086Y
Date of Loss:	31/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207854/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBF8492E</b>	Engine No:	ZD30019541N
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Chassis No:	JN1SC2F24Z0859536
Reg. Date:	29/03/2017 (Man. Year: 2016)	Odometer:	111842 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,152.24	2,626.59	12,525.65	82.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,130.00	1,670.00	59.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,952.24</b>	<b>3,756.59</b>	<b>14,195.65</b>	<b>79.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,000.00</b>		
	17,952.24	3,000.00	14,952.24	83.29
<b>+ GST 7.00/7.00% (\$\$)</b>	1,256.66	210.00	1,046.66	83.29
<b>Nett Amount (\$\$)</b>	<b>19,208.90</b>	<b>3,210.00</b>	<b>15,998.90</b>	<b>83.29</b>

INSPECTION

Date of Assignment: 02/11/2022

Date Inspected: 08/11/2022 Inspected At:

Carsmith Private Limited (HQ)  
13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ  
CENTRE  
Singapore 417807

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Nov 2022)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF8492E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Badly Dented	1,887.40 FL	*1,688.10 FL
2	2		*REAR GATE STOPPER RUBBER	Not Necessary	40.40 FL	*- FL
3	2		*REAR GATE STOPPER BRACKET	Not Necessary	389.40 FL	*- FL
4	3		*REAR GATE HINGES	Not Necessary	338.80 FL	*- FL
5	2		*REAR GATE SIDE LOCK	Not Necessary	137.40 FL	*- FL
6	2		*REAR GATE SAFETY LOCK	Not Necessary	144.80 FL	*- FL
7	1		*TAILLAMP LH	Cracked	297.20 FL	*208.00 FL
8	1		*TAILLAMP BRACKET LH	Repair	121.40 FL	*- FL
9	1		*TAILLAMP RH	Cracked	297.20 FL	*208.00 FL
10	1		*TAILLAMP BRACKET RH	Repair	121.40 FL	*- FL
11	2		*SIDE GATE	Not Necessary	5,973.00 FL	*- FL
12	1		*END PANEL	Bent	1,675.40 FL	*481.00 FL
13	1		*REAR FLOOR PANEL	Not Necessary	3,279.80 FL	*- FL
14	1		*REAR GATE ALUMINIUM CLADDING (SPECIAL TYPE)	Serviceable	580.00 FS	*- FS
15	1		*ALUMINIUM CLADDING RIVETS	Necessary	80.00 FS	*40.00 FS
16	1		*REAR GATE STICKER (70KM/H)	Necessary	45.00 FS	*10.00 FS
17	1		*REAR GATE STICKER (13 PAX)	Necessary	45.00 FS	*10.00 FS
18	1		*REAR GATE COMPANY STICKERS	Not Necessary	380.00 FS	*- FS
19	1		*REAR NUMBER PLATE W/GARNISH	Scratched	50.00 FS	*40.00 FS
20	1		*SET REVERSE SENSOR	Cracked	480.00 FS	*200.00 FS
21	1		*SET REVERSE SENSOR BRACKET	Not Necessary	159.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>16,622.60</b>	<b>2,885.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,470.36	258.51
<b>Total Parts (\$)</b>	<b>15,152.24</b>	<b>2,626.59</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	20.00
2	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	0.00
3	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,200.00	520.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	540.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,800.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >