



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303446

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 31/05/2023
Reference CC6/CTI22010973/Aya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YQ 5338H
Insured Veh. GBE 8035Y
Claim No. SNM22D207909/C02
Policy No. DMCVSNA00021512200
Accident Date 31/10/2022
Inspection Date 01/11/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22010973/Aya3q2 Date: 31/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 8035Y	Veh. Inspected	YQ 5338H	
Policy No.	DMCVSNA00021512200	Coverage (\$)	0.00	
Claim No.	SNM22D207909/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2755	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	JHHAGV4620K001602	Colour	SILVER	
Odometer	27376 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	145/80 R13	BRIDGESTONE	6 mm	
L/H Rear Tyre	145/80 R13	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/10/2022	Inspection Date	01/11/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 5338H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	DENTED	1,987.63	1,650.00
1	REAR TAILGATE EMBLEM DYNA (STICKER)	NECESSARY	69.40	69.40
1	REAR TAILGATE LOWER END PANEL	DENTED	898.40	495.00
2	REAR TAILGATE SIDE LOCK @\$298.30	O/S DENTED	596.60	298.30
2	REAR TAILGATE SIDE RUBBER STOPPER @\$31.20	O/SCUT	62.40	31.20
1	REAR NUMBER PLATE BRACKET	BENT	113.70	113.70
2	REAR TAILLAMP RH @\$248.20	DAMAGED	496.40	248.20
2	REAR TAILLAMP PANEL RH @\$259.10	O/S BENT	518.20	259.10
2	REAR TAILLAMP INNER COVER /GARNISH @\$121.30	NOT NECESSARY	242.60	-
2	REAR REFLECTOR LAMP @\$87.60	NOT NECESSARY	175.20	-
2	REAR NUMBER PLATE LAMP @\$98.10	NOT NECESSARY	196.20	-
1	REAR EXHAUST CATALYTIC CONVERTER	NOT NECESSARY	1,718.90	-
1	REAR SPARE TYRE LOCK	NOT NECESSARY	283.10	-
	LESS 25% DISCOUNT		-1,839.68	-791.23
			5,519.05	2,373.67
<u>SPECIAL NETT ITEMS</u>				
1	REAR SATEY ALIMINIUM BAR (SN)	BENT	950.00	850.00
1	REAR TAILGATE STICKER (COMPANY) (SN)	NECESSARY	500.00	350.00
1	REAR STICKER 60KM/H (SN)	NECESSARY	35.00	15.00
1	REAR TAILGATE INNER CHECKER PLATE (SN)	NOT NECESSARY	600.00	-
1	REAR FLOOR PANEL CHECKER PLATE (SN)	NOT NECESSARY	120.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			2,530.00	1,415.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING.		1,500.00	700.00
	LABOUR FOR SPRAYPAINTING.		1,000.00	600.00
	LABOUR FOR REMOVE & RENEW REAR SAETY ALIMINIUM BAR .		200.00	80.00
	WIRING CHECK.		80.00	30.00

Report Ref No. CC6/CTI22010973/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR REMOVE & RENEW REAR EXHAUST CATALYTIC CONVERTER .		300.00	80.00
	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS .		300.00	60.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
			3,480.00	1,600.00
GRAND TOTAL			11,529.05	5,388.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC6/CTI22010973/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YQ 5338H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YQ 5338H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

