Adjuster Report 2/3/23, 11:21 AM

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

OD

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No:

CC3/AIG22010974/AQCE2

Singapore 079120

Date:

03/02/2023

**REFERENCE** 

Date of Loss:

Insured/Claimant:

JUN NITTA 22/10/2022

Policy No: 2070060703-01

Claim No:

8839616338SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: Make & Model: S6825CD

(A)

AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17)

Nature of Claim:

Engine No:

CZD891677

11352 km

Reg. Date:

25/03/2020 (Man. Year: 2020)

Chassis No: Odometer:

No

WAUZZZF33L1078447

Colour: **Engine Capacity:**  Blue

1395 cc

Market Value/New Car Price: S\$120,000.00

Sum Insured (S\$):

**Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): **Engine Modification:** 

Footbrake (Serviceable): Yes

Pre-accident Condition:

Yes

Handbrake (Serviceable):

**CONDITION OF TYRES** 

215/65 R17

Yes

Rear Tyre Size:

215/65 R17

Front Tyre Size: Front Left Side:

Falken 6 mm

Rear Left Side: Rear Right Side:

Falken 6 mm Falken 6 mm

Front Right Side: Falken 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		21,017.00	5,194.96	15,822.04	75.28
Miscellaneous Items		0.00	0.00	0.00	
Labour		22,412.00	4,962.00	17,450.00	77.86
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	43,429.00	10,156.96	33,272.04	76.61
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	42,629.00	9,356.96	33,272.04	78.05
	+ GST 8.00/8.00% (S\$)	3,410.32	748.56	2,661.76	78.05
	Nett Amount (S\$)	46,039.32	10,105.52	35,933.80	78.05

**INSPECTION** 

Adjuster:

Date of Assignment:

03/11/2022

Premium Automobiles Pte Ltd (UBI)

Date Inspected:

02/11/2022

Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

6.0 days

**ADRIAN LING** 

Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,738.00 FS	*-FS
2	1		*REAR BUMPER SPOILER	Not Necessary	510.00 FS	*-FS
3	1		*REAR BUMPER ADAPTER - LH	Not Necessary	95.00 FS	*-FS
4	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	71.00 FS	*-FS
5	1		*REAR SIDE PANEL - LH	Repair	3,899.00 FS	*-FS
6	1		*REAR QUARTER WINDOW - LH	Not Necessary	683.00 FS	*-FS
7	1		*WINDOW PRIMER	Not Necessary	22.00 FS	*-FS
8	1		*REAR WHEEL SPOILER - LH	Not Necessary	44.00 FS	*-FS
9	1		*REAR SIDE MEMBER TRIM - LH	Not Necessary	189.00 FS	*-FS
10	1		*REAR WHEEL HOUSING LINER	Not Necessary	262.00 FS	*-FS
11	1		*REAR DOOR - LH	Dented	3,028.00 FS	*2,422.40 FS
12	1		*REAR OUTER DOOR SEAL - LH	Necessary	151.00 FS	*120.40 FS
13	1		*REAR DOOR CATCH	Not Necessary	134.00 FS	*- FS
14	1		*REAR SILL PANEL SEAL - LH	Not Necessary	151.00 FS	*-FS
15	1		*REAR INNER DOOR SEAL	Not Necessary	213.00 FS	*- FS
16	1		*REAR DOOR COVER - LH LOWER	Distorted	368.00 FS	*294.00 FS
17	1		*FRONT DOOR COVER - LH LOWER	Distorted	390.00 FS	*312.00 FS
18	1		*REAR DOOR HANDLE BASE	Not Necessary	182.00 FS	*- FS
19	1		*REAR DOOR BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
20	1		*REAR DOOR HANDLE - LH	Repair	223.00 FS	*- FS
21	1		*REAR DOOR HOUSING - LH	Not Necessary	31.00 FS	*- FS
22	1		*RAER WINDOW REGULATOR MOTOR - LH	Not Necessary	300.00 FS	*- FS
23	1		*REAR DOOR CONTROL UNIT	Not Necessary	464.00 FS	*- FS
24	1		*REAR DOOR PANEL - LH	Not Necessary	2,659.00 FS	*- FS
25	1		*REAR WINDOW SLOT SEAL TRIM STRIP - LH OUTER	Not Necessary	305.00 FS	*- FS
26	1		*REAR WINDOW GUIDE TRIM STRIP - LH	Not Necessary	170.00 FS	*- FS
27	2		*REAR WHEEL COVER - LH / RH	N/S Missing / O/S Necessary	1,132.00 FS	*904.80 FS
28	1		*REAR CROSS PANEL	Not Necessary	445.00 FS	*- FS
29	1		*RAER ALUMINIUM RIM	Cut	1,414.00 FS	*1,131.20 FS
30	1		*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
31	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
32	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
33	1		*STONE CHIP	Not Necessary	180.00 FS	*-FS
34	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*-FS
35	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*-FS
36	1		*SUNDRIES	Necessary	500.00 FS	*10.16 FS
37	1		*REAR WINDOW REGULATOR - LH	Not Necessary	302.00 FS	*-FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 21,017.00 5,194.96

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KID SENSOR	CK New	360.00	360.00
2	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	0.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, C PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC		1,600.00	0.00
6	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTI AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	E <b>M</b> New	400.00	280.00
7	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	0.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLIN RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL A PARTS REMOVED	G	8,000.00	1,500.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR LHS FRONT DOOR, TWO DOOR COVERS, DOOR HANDLE, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS	, New	9,000.00	2,350.00
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross La	bour Cost (S\$)	22,412.00	4,962.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.