

ASS. REC. BY:

REF:

T11 / 220109761kp
CARB

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

867k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

08/28

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

17/11 21:00 @ 4000 Curb

Veh No:

SJ14563325 Yr Regn: 08, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Estimo c.c. 2362

Colour

M. Gray A/C: Insured / Std / NI / NA

Sp. Reading

257288 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ACR50 7062253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Rotalla 215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

7

mm

L/Bal.

3

mm

L/Bal.

7

mm

D.O.A.

1/11/22

D.O.I.

3/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS St

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 066/11/2022

Page : 1

M/S INDIA INTERNATIONAL INSURANCE PTE LTD
64 CEICIL STREET #04/#05
IOB BUILDING
SINGAPORE 049711

Date : 03/11/2022

ACCIDENT REPAIR ON : SJH 6332 S - ESTIMA AERAS 2.4 A
CHASSIS NO : ACR507062253
DATE OF ACCIDENT : 01/11/2022

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

		S\$	S\$
1 TAILGATE	1619	1,650.23	✓
2 REAR EMBLEM "ESTIMA"		67.09	✓
3 REAR EMBLEM "AERAS"		54.30	✓
4 REAR EMBLEM "HYBRID"		54.30	✓
3 INNER LOCK		509.23	✓
4 REAR BUMPER		647.69	✓
5 REAR BUMPER SPONGE		101.12	X
6 BUMPER RETAINER LEFT		78.60	X
7 BUMPER RETAINER RIGHT		78.60	✓
8 REVERSE SENSOR	1 SET S/NETT	250.00	200.00
9 END PANEL		649.04	✓
10 END PANEL TOP GARNISH	308.20	323.09	✓
11 WEATHERSTRIP		399.78	50.00 199.89
12 WINDSCREEN GLUE	1 TUBE S/NETT	40.00	✓
		4,613.07	
	LESS : 25%	1,153.27	
		3,459.80	
		3,749.80	

LABOUR CHARGES :

13 STRIP / REFIT REAR WINDSCREEN	120.00
14 KNOCKING PUSH OUT REAR ACCIDENT PARTS CUT & WELD END PANEL STRIP / REFIT ABOVE ACCESSORIES	700.00
15 TO PUTTY & SPRAY PAINT & ANTI RUST ON ALL ACCIDENT DAMAGE PARTS & OTHER ACCIDENT AFFECTED AREAS	800.00
	900.00
	5,749.80



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: