

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP19100021

Date: 20 DEC 2019

*Heng Si Kiat*

*c/o Hup Ley Huat Motor Spray Painting Services*

*Blk 1, #01- 35*

*Kaki Bukit Ave 6*

*Singapore 417883*

## THIRD PARTY SURVEY

ACCIDENT OCCURED ON 14 OCT 2019

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services

Blk 1, #01- 35

Kaki Bukit Ave 6

Singapore 417883

As per your instruction dated

21 OCT 2019

with regard to the above matter.

We have carried out a physical inspection on the said

SLU5507U

We enclosed herewith our report and findings as follows:

## 1. VEHICLE PARTICULARS

Registration No : SLU5507U  
Model : TOYOTA VIOS E AUTO  
Year / Capacity : Feb 2009 / 1497 cc  
Chassis No : MR053HY9305100794

Engine No : 1NZX866868  
Mileage : 351 742 km  
Colour : Metallic White

## 2. TYRES CONDITION

|             | <u>Size</u> | <u>Made</u> | <u>Balance</u> | <u>Rim</u> |
|-------------|-------------|-------------|----------------|------------|
| FRONT O/S : | 195/50/R15  | Bridgeston  | 9.00 mm        | Sport      |
| Front O/S : | 195/50/R15  | Bridgeston  | 9.00 mm        | Sport      |
| FRONT N/S : | 195/50/R15  | Bridgeston  | 9.00 mm        | Sport      |
| Front N/S : | 195/50/R15  | Bridgeston  | 9.00 mm        | Sport      |

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the Rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLU5507U

SPARE PARTS

| QTY               | PARTS DESCRIPTION                     | CONDITION              | Workshop Estimation (\$) | Our Revised Estimation (\$) |
|-------------------|---------------------------------------|------------------------|--------------------------|-----------------------------|
| <u>List Items</u> |                                       |                        |                          |                             |
| 1 pc              | Boot lid                              | distorted              | \$ 781.70                | \$ 781.70 ✓                 |
| 2 pcs             | Boot lid hinge                        | bent/deformed          | \$ 322.80                | \$ 322.80 X nn              |
| 2 pcs             | Boot lid stopper                      | deformed               | \$ 95.40                 | \$ 95.40 X nn               |
| 1 pc              | Boot lid lock                         | distorted              | \$ 123.05                | \$ 123.05 ✓                 |
| 1 pc              | Boot lid lock striker                 | distorted              | \$ 121.01                | \$ 121.01 X nn              |
| 1 pc              | Boot lid emblem "Vios"                | necessary              | \$ 32.90                 | \$ 32.90 ✓                  |
| 1 pc              | Boot lid emblem "1.5"                 | necessary              | \$ 29.80                 | \$ 29.80 ✓                  |
| 1 pc              | Boot lid emblem "E"                   | necessary              | \$ 57.40                 | \$ 57.40 ✓                  |
| 1 pc              | Bot lid center garnish                | deformed               | \$ 187.70                | \$ 187.70 ✓                 |
| 2 pcs             | Boot lid center garnish clips         | necessary              | \$ 25.80                 | \$ 25.80 15 ✓               |
| 1 pc              | Boot lid weather stripe               | deformed               | \$ 187.25                | \$ 187.25 ✓                 |
| 2 pcs             | Tail lamp assy                        | distorted              | \$ 561.70                | \$ 561.70 ✓                 |
| 2 pcs             | Tail lamp sealant                     | necessary              | \$ 100.00                | \$ 100.00 X nn              |
| 4 pcs             | Tail lamp clips                       | necessary              | \$ 51.60                 | \$ 51.60 X nn               |
| 2 pcs             | Tail lamp base panel                  | dent/distorted         | \$ 363.20                | \$ 363.20 X R               |
| 1 pc              | Rear bumper fascia                    | bent/deformed          | \$ 381.85                | \$ 381.85 ✓                 |
| 2 pcs             | Rear bumper side retainer             | distorted              | \$ 246.10                | \$ 246.10 ✓                 |
| 2 pcs             | Rear bumper side attachment           | distorted              | \$ 242.40                | \$ 242.40 X nn              |
| 2 pcs             | Rear bumper reflector                 | deformed               | \$ 282.80                | \$ 282.80 ✓                 |
| 8 pcs             | Rear bumper clips                     | necessary              | \$ 103.20                | \$ 103.20 30 ✓              |
| 2 pcs             | Rear bumper stay bracket              | deformed               | \$ 344.80                | \$ 344.80 X nn              |
| 1 pc              | Rear end panel                        | dent/distorted         | \$ 671.40                | \$ 671.40 ✓                 |
| 1 pc              | Rear end panel top trim               | deformed               | \$ 289.90                | \$ 289.90 203 ✓             |
| 4 pcs             | Rear end panel top trim clips         | necessary              | \$ 51.60                 | \$ 51.60 15 ✓               |
| 2 pcs             | Rear fender LH & RH                   | bent - repair          | \$ 1,944.90              | \$ 1,944.90 X R             |
| 2 pcs             | Rear fender inner trim board          | bent/deformed          | \$ 1,163.90              | \$ 1,163.90 X nn            |
| 12 pcs            | Rear fender inner trim board clips    | necessary              | \$ 154.80                | \$ 154.80 X nn              |
| 1 pc              | Rear floor panel                      | deformed               | \$ 987.72                | \$ 987.72 X R               |
| 1 pc              | Rear floor panel board                | deformed               | \$ 182.40                | \$ 182.40 X nn              |
| 1 pc              | Rear floor panel insulator cloth      | deformed               | \$ 281.80                | \$ 281.80 X nn              |
| 2 pcs             | Rear floor panel side panel - RH & LH | distorted              | \$ 379.80                | \$ 379.80 X nn              |
| 1 pc              | Rear tool tray sponge ( center)       | deformed               | \$ 289.90                | \$ 289.90 X nn              |
| 1 pc              | Rear tool tray sponge ( LH )          | deformed               | \$ 272.40                | \$ 272.40 X nn              |
| 1 pc              | Rear tool tray sponge ( RH )          | deformed               | \$ 281.95                | \$ 281.95 X nn              |
| 1 pc              | Rear exhaust silencer                 | dent/distorted         | \$ 781.50                | \$ 781.50 X nn              |
| 1 pc              | Rear exhaust silencer chrome pipe     | dent/distorted         | \$ 171.85                | \$ 171.85 X nn              |
| 2 pcs             | Rear exhaust silencer rubber          | dent/distorted         | \$ 183.80                | \$ 183.80 X nn              |
| 2 pcs             | Rear number plate lamp                | electronically shocked | \$ 166.80                | \$ 166.80 X nn              |
| Parts Sub-Total   |                                       |                        | \$ 12,898.88             | \$ 10,953.98                |
| Discount 25.00%   |                                       |                        | \$ 3,224.72              | \$ 2,738.50                 |
|                   |                                       |                        | \$ 9,674.16              | \$ 8,215.49                 |

Vehicle Number : SLU5507U

**SPARE PARTS**

| QTY                       | PARTS DESCRIPTION                | CONDITION              | Workshop Estimation (S\$) | Our Revised Estimation (S\$) |
|---------------------------|----------------------------------|------------------------|---------------------------|------------------------------|
| <u>Special Nett Items</u> |                                  |                        |                           |                              |
| 1 pc                      | Number plate                     | distorted              | \$ 65.00                  | \$ <del>65.00</del> 65.00X   |
| 1 pc                      | Number plate casing              | dent/distorted         | \$ 45.00                  | \$ <del>45.00</del> 45.00X   |
| 1 set                     | Reverse sensor with control unit | electronically shocked | \$ 250.00                 | \$ <del>250.00</del> 220.00  |
| Special Nett Sub-Total    |                                  |                        | \$ 360.00                 | \$ 330.00                    |
| Spare Parts Total         |                                  |                        | \$ 10,034.16              | \$ 8,545.49                  |

**LABOUR COST**

| S/No                  | JOB DESCRIPTIONS                                                                                                              | Workshop Estimation (S\$) | Our Revised Estimation (S\$)         |
|-----------------------|-------------------------------------------------------------------------------------------------------------------------------|---------------------------|--------------------------------------|
| Spare Parts Total c/f |                                                                                                                               | \$ 10,034.16              | \$ 8,545.49                          |
| 1                     | Towing                                                                                                                        | \$ 120.00                 | \$ <del>120.00</del> 80 120.00       |
| 2                     | To check & repair snap wiring                                                                                                 | \$ 180.00                 | \$ <del>180.00</del> 30 150.00       |
| 3                     | To remove and refix interior upholstery                                                                                       | \$ 180.00                 | \$ <del>180.00</del> 50 150.00       |
| 4                     | To remove & replace reverse sensor                                                                                            | \$ 150.00                 | \$ <del>150.00</del> 30 120.00       |
| 5                     | To remove/replace exhaust silencer & straighten exhaust center pipe                                                           | \$ 180.00                 | \$ <del>180.00</del> X 150.00        |
| 6                     | To respray affected areas                                                                                                     | \$ 1,800.00               | \$ <del>1,800.00</del> 800 1,600.00  |
| 7                     | To renew damaged parts, straightener and repair rear wheel housing panel, rear chassis member, rear door & aligned all parts. | \$ 2,000.00               | \$ <del>2,000.00</del> 1000 1,800.00 |
| 8                     | To tuff coat affected areas                                                                                                   | \$ 180.00                 | \$ <del>180.00</del> 30 150.00       |
| 9                     | To remove and transfer bootlid mechanism                                                                                      | \$ 150.00                 | \$ <del>150.00</del> 50 120.00       |
| Total                 |                                                                                                                               | \$ 14,974.16              | \$ 12,905.49                         |

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 10,000.00

Fong Kok Heng  
Qualified Appraiser



7 days