



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SMW 1022E

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	RR RH DOOR (SN)	DENTED	1,395.75
1	RH COVERING PRIMEND (SN)	NECESSARY	48.75
1	FRT RH DOOR (SN)	DENTED	1,130.75
1	RH DOOR OUTER HANDLE PRIMED (SN)	CUT	97.45
1	SUNDRIES (SN)	NECESSARY	80.00
			2,752.70
	<b><u>LABOUR</u></b>		
	REPLACE BOTH RIGHT DOOR AND ATTACHMENTS INCLUDE KNOCKING OUT DENTS CAUSED BY ACCIDENT.		1,700.00
	PAINTING BOTH RIGHT DOOR, LOWER SKIRTING RIGHT AND BOTH OUTER SIDE HANDLE.		1,770.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (2 PANEL).		236.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION. (2 DOORS).		1,062.00
	TO CONDUCT WATER LEAK TESTS.		75.00
			4,843.00
	<b>GRAND TOTAL</b>		<b>7,595.70</b>
<b>RECOMMENDED COST OF REPAIRS</b>			<b>7,595.70</b>

Report Ref No. CS1/SPF22010983/Dny3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.