



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 2075J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	DISTORTED /TORN	2,175.00	1,850.00
1	FRONT BUMPER SIDE GRILLE -RH (CONSISTENT)	GRAZED / TORN	195.00	195.00
2	FRONT BUMPER PDC SENSOR @\$285.00 (CONSISTENT)	SHORTED (1 PCS ONLY)	570.00	225.00
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	192.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	1,075.00	-
2	FRONT BUMPER SIDE RETAINER -R/L @\$65.00 (CONSISTENT)	O/S CRACKED	130.00	65.00
1	FRONT BUMPER LOWER SPOILER (CONSISTENT)	GRAZED	835.00	835.00
1	FRONT FENDER -RH (CONSISTENT)	BADLY DENTED	1,055.00	1,055.00
1	FRONT FENDER PROTECTOR (CONSISTENT)	DISTORTED	535.00	535.00
1	FRONT FENDER INNER SHIELD (CONSISTENT)	DISTORTED	286.00	286.00
1	FRONT FENDER STAY (CONSISTENT)	NOT NECESSARY	115.00	-
1	FRONT FENDER EMBLEM (CONSISTENT)	NECESSARY	85.00	85.00
1	FRONT HEADLAMP ASSY (CONSISTENT)	HOLDER CRACKED	4,355.00	3,450.00
1	FRONT SPORT WHEEL -RH (CONSISTENT)	NOT NECESSARY	1,150.00	-
1	FRONT SHOCK ABSORBER -RH (CONSISTENT)	NOT NECESSARY	695.00	-
	LESS 10% DISCOUNT		-1,344.80	-858.10
			12,103.20	7,722.90
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	60.00	50.00
1	SET FRONT FENDER PROTECTOR CLIP (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	SET FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NECESSARY	60.00	50.00
			180.00	100.00
LABOUR				
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	20.00
	TO TUFF KOTE .		60.00	30.00
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS .		800.00	450.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS .		800.00	300.00
			1,830.00	800.00
GRAND TOTAL			14,113.20	8,622.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CC4/ASM22010990/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.