



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 9382A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	DEFORMED	2,201.00	2,201.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	201.00	-
2	REAR BUMPER GUIDE SECTION -LH/RH (SN)	NOT NECESSARY	36.00	-
2	REAR BUMPER LOCKING MECHANISM -LH/RH (SN)	NOT NECESSARY	67.00	-
1	REAR BUMPER SPOILER (SN)	CUT	264.00	263.50
2	REAR BUMPER REFLECTOR -LH/RH (SN)	NOT NECESSARY	92.00	-
1	REAR BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	642.00	-
2	REAR BUMPER BRACKET-LH/RH (SN)	NOT NECESSARY	30.00	-
2	REAR PARKING AID SENSOR -INNER /OUTER (SN)	NOT NECESSARY	531.00	-
4	REAR PARKING AID SEAL RING (SN)	NOT NECESSARY	10.00	-
1	SUNDRIES (SN)	NOT NECESSARY	400.00	-
			4,474.00	2,464.50
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER REAR PARKING AID .		280.00	280.00
	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED.		1,050.00	700.00
	TO RESPRAY REAR BUMPER .		900.00	700.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			2,422.00	1,872.00
GRAND TOTAL			6,896.00	4,336.50
RECOMMENDED COST OF REPAIRS				4,336.50

Report Ref No. CS/SMO22010997/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.