

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22010999/KWP3Q2  
**Date:** 15/11/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00001802201
Claimant Vehicle No :	SJY7004T	Insured Vehicle No :	YL3591G
Date of Loss:	02/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D207903/C02/LEEPG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY7004T	Engine No:	R18A15000270
Make & Model:	HONDA CIVIC, 1.8 L 5AT (A)	Chassis No:	JHMFD1630AS200098
Reg. Date:	24/09/2010 (Man. Year: 2009)	Odometer:	191307 km
Colour:	Metallic Red		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Triangle 4 mm	Rear Left Side:	Triangle 3 mm
Front Right Side:	Triangle 4 mm	Rear Right Side:	Triangle 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,672.80	2,718.76	6,954.04	71.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,180.00	770.00	39.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,622.80</b>	<b>3,898.76</b>	<b>7,724.04</b>	<b>66.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>(S\$)</b>	11,622.80	3,000.00	8,622.80	74.19
<b>+ GST 7.00/7.00% (S\$)</b>	813.60	210.00	603.60	74.19
<b>Nett Amount (S\$)</b>	<b>12,436.40</b>	<b>3,210.00</b>	<b>9,226.40</b>	<b>74.19</b>

### INSPECTION

Date of Assignment:	03/11/2022		
Date Inspected:	08/11/2022	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG

**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2022)
<b>Parts:</b> 143	HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJY7004T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	953.00 FL	*606.20 FL
2	1		*BONNET INSULATOR	Serviceable	225.00 FL	*- FL
3	1		*FRONT BUMPER	Cracked	981.00 FL	*638.40 FL
4	2		*FRONT BUMPER SIDE RETAINER	Serviceable	110.00 FL	*- FL
5	1		*FRONT BUMPER TOP PANEL	Repair	189.00 FL	*- FL
6	1		*RADIATOR GRILLE	Cracked	325.00 FL	*224.60 FL
7	1		*RADIATOR GRILLE HONDA LOGO	Necessary	55.00 FL	*55.00 FL
8	1		*SUPPORT PANEL	Repair	687.00 FL	*- FL
9	1		*FRONT LICENCE PLATE GARNISH	Serviceable	106.00 FL	*- FL
10	1		*HEADLAMP O/S	Cracked	1,345.00 FL	*912.00 FL
11	1		*HEADLAMP LOWER BRACKET O/S	Serviceable	59.00 FL	*- FL
12	1		*FRONT BUMPER TOW COVER	Serviceable	49.00 FL	*- FL
13	1		*FRONT BUMPER LOWER LIP	Serviceable	214.00 FL	*- FL
14	2		*FRONT FOGLAMP	Serviceable	458.00 FL	*- FL
15	2		*FRONT FOGLAMP OUTER GARNISH	Serviceable	358.00 FL	*- FL
16	1		*RADIATOR ASSY	Serviceable	921.00 FL	*- FL
17	1		*AIRCON CONDENSOR	Serviceable	1,021.00 FL	*- FL
18	2		*RADIATOR /CONDENSOR FAN	Serviceable	1,086.00 FL	*- FL
19	1		*RADIATOR FAN COWLING	Serviceable	432.00 FL	*- FL
20	1		*FRONT BUMPER REINFORCEMENT	Repair	538.00 FL	*- FL
21	1		*HEADLAMP PANEL O/S	Repair	194.00 FL	*- FL
22	1		*FRONT FENDER O/S	Bent	1,067.00 FL	*450.50 FL
23	1		*FRONT FENDER TOP MOULDING O/S	Dented	98.00 FL	*98.00 FL
24	2		*BONNET HINGE	Distorted	290.00 FL	*290.00 FL
25	10		*BONNET INSULATOR CLIPS	Necessary	45.00 FS	*45.00 FS
26	12		*FRONT BUMPER CLIPS	Necessary	54.00 FS	*54.00 FS
27	1		*FRONT LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS
28	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
29	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>12,025.00</b>	<b>3,373.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	2,352.20	654.94
<b>Total Parts (S\$)</b>	<b>9,672.80</b>	<b>2,718.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	500.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS	New	50.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	800.00	600.00
4	TO RUST PROOF ACCIDENT AFFECTED PORTIONS	New	100.00	60.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,950.00</b>
				<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >