

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011002/EQP3Q2**Date:** 05/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00011842201
<b>Claimant Vehicle No :</b>	SNF7827M	<b>Insured Vehicle No :</b>	GY7654C
Date of Loss:	02/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D207899/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNF7827M</b>		
Make & Model:	BMW 218i, 1.5 (A)	Engine No:	0471NJ22B38A15F04N
Reg. Date:	22/06/2022 (Man. Year: 2021)	Chassis No:	WBA6V720005U68411
Colour:	Black	Odometer:	3396 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,331.70	1,331.70	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,060.00	3,852.00	2,208.00	36.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,391.70</b>	<b>5,183.70</b>	<b>2,208.00</b>	<b>29.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	517.42	362.86	154.56	29.87
<b>Nett Amount (S\$)</b>	<b>7,909.12</b>	<b>5,546.56</b>	<b>2,362.56</b>	<b>29.87</b>

INSPECTION

Date of Assignment:	03/11/2022	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Date Inspected:	04/11/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
Parts:	143	BMW 218I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF7827M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RR LH DOOR	Dented	1,159.75 FS	*1,159.75 FS
3	1		*LH SEALING COLUMN B BOTTOM	Necessary	57.90 FS	*57.90 FS
4	1		*REAR DOOR JOINT SEAL	Necessary	34.05 FS	*34.05 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					1,331.70	1,331.70

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE LEFT REAR DOOR	New	1,275.00	0.00
2	TO RESPRAY LEFT REAR DOOR	New	885.00	0.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING INCLUDING RESET AND CHECK AIR BAG FOR PROPER FUNCTION	New	295.00	280.00
6	TO REPLACE REAR LH DOOR AND ATTACHMENTS INCLUDE MARKING GOOD THE REAR LH FENDER AND KNOCKING OUT DENTS CAUSED BY THE ACCIDENT	New	1,275.00	1,275.00
7	TO SPRAY PAINT REAR LH DOOR AND REAR LH FENDER	New	1,681.00	1,681.00
<b>Gross Labour Cost (S\$)</b>			<b>6,060.00</b>	<b>3,852.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >