

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG22003751/RVY3E2-1**Date:** 05/12/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29154072MKF

Claimant Vehicle No : SMF180C**Insured Vehicle No :** YP1505Z

Date of Loss: 20/04/2022

Nature of Claim: TP Claim No: 641109

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMF180C**

Make & Model: LEXUS ES300H, 2.5 Luxury (A)

Engine No: A25AN289437

Reg. Date: 22/04/2021 (Man. Year: 2021)

Chassis No: JTHB21B1902135544

Colour: Grey

Odometer: 35838 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18

Rear Tyre Size: 235/45 R18

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,101.75	5,520.82	7,580.93	57.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	1,480.00	2,960.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,541.75	7,000.82	10,540.93	60.09
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	17,541.75	5,600.00	11,941.75	68.08

INSPECTION

Date of Assignment: 22/04/2022

Date Inspected: 22/04/2022 Inspected At:

Eng Soon Painting Services (HQ)
393J WOODLANDS ROAD
Singapore 677978

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2022)
Parts:	143	LEXUS ES300H 2.5 Luxury (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF180C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ASSEMBLY	Bent	2,150.00 FL	*2,150.00 FL
2	1		*FRONT DOOR WEATHERSTRIP	Bent	244.00 FL	*244.00 FL
3	1		*FRONT DOOR CHECKER	Not Necessary	114.00 FL	*- FL
4	2		*FRONT DOOR HINGE	Not Necessary	288.00 FL	*- FL
5	2		*FRONT DOOR STOPPER	Bent	168.00 FL	*168.00 FL
6	1		*FRONT DOOR INNER LOCK	Bent	345.00 FL	*345.00 FL
7	1		*FRONT DOOR LOCK STRIKER	Not Necessary	79.00 FL	*- FL
8	1		*FRONT DOOR OUTER HANDLE	Bent	425.00 FL	*425.00 FL
9	1		*FRONT DOOR CONTROL UNIT	Not Necessary	341.00 FL	*- FL
10	1		*FRONT DOOR SPEAKER	Not Necessary	188.00 FL	*- FL
11	1		*FRONT DOOR LOWER RUBBER BEADING	Warped / Deformed	122.00 FL	*122.00 FL
12	1		*FRONT DOOR FRAME TOP RUBBER	Warped / Deformed	84.00 FL	*84.00 FL
13	1		*FRONT DOOR FRAME CHROME	Grazed / Deformed	320.00 FL	*320.00 FL
14	1		*FRONT DOOR WINDOW REGULATOR	Distrupted	341.00 FL	*341.00 FL
15	1		*FRONT DOOR WINDOW REGULATOR MOTOR	Not Necessary	476.00 FL	*- FL
16	1		*FRONT DOOR WINDOW GLASS CHANNEL RUBBER	Not Necessary	188.00 FL	*- FL
17	1		*FRONT DOOR WINDOW GLASS CHANNEL BRACKET	Not Necessary	164.00 FL	*- FL
18	1		*FRONT DOOR WINDOW GLASS OUTER CHROME	Grazed / Deformed	228.00 FL	*228.00 FL
19	1		*FRONT DOOR PILLAR	Repair	446.00 FL	*- FL
20	1		*SIDE MIRROR	Distorted	749.00 FL	*749.00 FL
21	1		*SIDE MIRROR COVER	Grazed / Deformed	367.00 FL	*367.00 FL
22	1		*REAR DOOR ASSEMBLY	Bent / Distorted	3,520.00 FL	*1,427.10 FL
23	1		*REAR DOOR WEATHERSTRIP	Warped / Deformed	244.00 FL	*244.00 FL
24	1		*REAR DOOR CHECKER	Not Necessary	122.00 FL	*- FL
25	1		*REAR DOOR HINGE	Bent / Distorted	147.00 FL	*147.00 FL
26	1		*REAR DOOR FRAME CHROME	Not Necessary	370.00 FL	*- FL
27	1		*REAR DOOR WINDOW GLASS CHROME	Not Necessary	227.00 FL	*- FL
28	1		*REAR DOOR INNER LOCK	Not Necessary	345.00 FL	*- FL
29	1		*REAR DOOR WINDOW REGULATOR	Not Necessary	341.00 FL	*- FL
30	1		*REAR DOOR WINDOW REGULATOR MOTOR	Not Necessary	476.00 FL	*- FL
31	1		*REAR FENDER	Not Necessary	1,850.00 FL	*- FL
32	1		*TYRE ASSEMBLY - REAR	Not Necessary	420.00 FS	*- FS
33	1		*REAR WHEEL RIM ASSY (SPORT)	Not Necessary	1,080.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,969.00	7,361.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,867.25	1,840.28
Total Parts (\$\$)	13,101.75	5,520.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	120.00	0.00
2	TO CHECK MIRROR WIRING SYSTEM	New	180.00	60.00
3	TO REMOVE AND TRANSFER FRONT AND REAR DOOR MECHANISM	New	480.00	160.00
4	TO RESPRAY AFFECTED AREAS	New	1,600.00	600.00
5	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR & ALIGNED ALL PARTS	New	1,600.00	500.00
6	TO RESET ELECTRICAL MODULE SYSTEM	New	280.00	100.00
7	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
Gross Labour Cost (\$)			4,440.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >